Last Vehicle Status Update: May 31, 2024 10:33 PM
*Note: Do not use as a pressure gauge

Refresh

Odometer

40246 Miles

Fuel Level

E \ / F

Fuel Level: **42%**
Fuel Range: **251 Miles to empty**

Tire Pressure (PSI)*

34   34
33   33

Recommended Tire
Pressure(cold)
Front : **35** | Rear : **35**

Oil Life Remaining

84%

Diesel Exhaust Fluid

Exhaust Fluid Level: **73%**
Distance To Empty:
6000 Miles

12V Battery

Battery State of Charge : **52%**
Battery Voltage : **14.3V**

60-Day VHA/DTC History

Last Vehicle Health Update: May 31, 2024 04:48 PM

April 2024

Sun	Mon	Tue	Wed	Thu
	1	2 ⚠️	3 ⚠️	4
7 ⚠️	8 ⚠️	9	10 OTA	11
14	15	16 ⚠️	17	18
21	22 ⚠️	23	24	25
28	29	30		

May 2024

Sun	Mon	Tue	Wed	Thu
			1	2
5	6	7	8	9
12	13	14	15	16
19	20	21	22	23
26	27	28	29 ⚠️	30

June 2024

Sun	Mon	Tue	Wed	Thu
2	3	4	5	6
9	10	11	12	13
16	17	18	19	20
23	24	25	26	27
30				

Vehicle Health Alerts (VHA) and Diagnostic Trouble Codes (DTC)

Date	Time	Odometer	Event Description	⬍★	⬍ Module		⬍ DTC	: FT : SB	⬍ TSB/GSB/SSM		✓ Send to Search	Description

May 31, 2024

Select All

Time: 09:14 AM
Odometer: 40246 mi

★	**HCM**	|	**B1D65** : **87** : **08**	Right Headlamp Swiveling Motor
★	**HCM**	|	**B1439** : **87** : **08**	Right Levelling Actuator
★	**PCM**	|	**P2601** : **00** : **2E**	Coolant Pump 'A' Control Circuit Performance/Stuck Off
★	**PSCM**	|	**U3003** : **68** : **2E**	Battery Voltage

May 29, 2024

Select All

Time: 05:34 PM
Odometer: 40246 mi

★	**CMR**	|	**B15E1** : **97** : **0E**	SSM	Driver Side LED
★	**IPMA**	|	**U0415** : **86** : **2C**	TSB	Invalid Data Received From Anti-Lock Brake System (ABS) Control Module
★	**PCM**	|	**P2601** : **00** : **2C**		Coolant Pump 'A' Control Circuit Performance/Stuck Off
★	**TCM**	|	**U0422** : **00** : **28**		Invalid Data Received From Body Control Module

May 10, 2024

Time: 11:00 AM
Odometer: 40245 mi

⚠ No DTCs Present

April 22, 2024

Select All

Time: 06:52 AM
Odometer: 40136 mi

HCM	|	B1D64 : 87 : 08		Left Headlamp Swiveling Motor
HCM	|	B1439 : 87 : 08		Right Levelling Actuator
SCCM	|	U2101 : 00 : 28	SSM	Control Module Configuration Incompatible
PCM	|	U1022 : 00 : 28		Invalid Internal Control Module Monitoring Data Received from Body Control Module
HCM	|	B1D65 : 87 : 08		Right Headlamp Swiveling Motor
OCSM	|	U024C : 00 : 28		Lost Communication with Seat Control Module 'H'

April 16, 2024

Time : 06:57 AM
Odometer :
39813 mi

HCM	B1D64 : 87 : 08			Left Headlamp Swiveling Motor
HCM	B1439 : 87 : 08			Right Levelling Actuator
SCCM	U2101 : 00 : 28	SSM		Control Module Configuration Incompatible
PCM	U1022 : 00 : 28			Invalid Internal Control Module Monitoring Data Received from Body Control Module
HCM	B1D65 : 87 : 08			Right Headlamp Swiveling Motor
OCSM	U024C : 00 : 28			Lost Communication with Seat Control Module 'H'
PSCM	U0415 : 00 : 28	TSB		Invalid Data Received From Anti-Lock Brake System (ABS) Control Module

April 13, 2024

Select All

Time : 01:05 PM
Odometer :
39721 mi

★ PSCM	U0415 : 00 : **28**	TSB		Invalid Data Received From Anti-Lock Brake System (ABS) Control Module
HCM	B1D64 : 87 : 08			Left Headlamp Swiveling Motor
HCM	B1439 : 87 : 08			Right Levelling Actuator
HCM	B14DC : 87 : 08			Right Headlamp Driver Control System
HCM	B1D65 : 87 : 08			Right Headlamp Swiveling Motor
OCSM	U024C : 00 : 28			Lost Communication with Seat Control Module 'H'
PCM	U1022 : 00 : 28			Invalid Internal Control Module Monitoring Data Received from Body Control Module
SCCM	U2101 : 00 : 28	SSM		Control Module Configuration Incompatible

Time : 07:07 AM
Odometer :
39685 mi

★ PCM	U1022 : 00 : **28**			Invalid Internal Control Module Monitoring Data Received from Body Control Module
★ **PSCM**	**U0415 : 00 : 2E**	TSB		Invalid Data Received From Anti-Lock Brake System (ABS) Control Module
HCM	B1D64 : 87 : 08			Left Headlamp Swiveling Motor
HCM	B1439 : 87 : 08			Right Levelling Actuator
HCM	B14DC : 87 : 08			Right Headlamp Driver Control System
HCM	B1D65 : 87 : 08			Right Headlamp Swiveling Motor
OCSM	U024C : 00 : 28			Lost Communication with Seat Control Module 'H'
PSCM	U3003 : 68 : 28			Battery Voltage
SCCM	U2101 : 00 : 28	SSM		Control Module Configuration Incompatible

April 10, 2024

Time : 04:09 PM   `OTA`   OTA On-Vehicle Activity-Update Activation is finished

Time : 04:06 PM   `OTA`   OTA On-Vehicle Activity-Vehicle Activation Start

April 08, 2024   ☐ Select All

Time : 05:03 PM
Odometer : 39385 mi

★	PCM	|	U1022 : 00 : 2E		☐ ⚠️	Invalid Internal Control Module Monitoring Data Received from Body Control Module
	HCM	|	B1439 : 87 : 08		☐ ⚠️	Right Levelling Actuator
	HCM	|	B14DC : 87 : 08		☐ ⚠️	Right Headlamp Driver Control System
	HCM	|	B1D65 : 87 : 08		☐ ⚠️	Right Headlamp Swiveling Motor
	HCM	|	B1D64 : 87 : 08		☐ ⚠️	Left Headlamp Swiveling Motor
	OCSM	|	U024C : 00 : 28		☐ ⚠️	Lost Communication with Seat Control Module 'H'
	PSCM	|	U3003 : 68 : 28		☐ ⚠️	Battery Voltage
	SCCM	|	U2101 : 00 : 28	SSM	☐ ⚠️	Control Module Configuration Incompatible

April 07, 2024   ☐ Select All

Time : 06:25 AM
Odometer : 39313 mi

★	HCM	|	B14DC : 87 : 08		☐ ⚠️	Right Headlamp Driver Control System
	HCM	|	B1D64 : 87 : 08		☐ ⚠️	Left Headlamp Swiveling Motor
	HCM	|	B1439 : 87 : 08		☐ ⚠️	Right Levelling Actuator
	HCM	|	B1D65 : 87 : 08		☐ ⚠️	Right Headlamp Swiveling Motor
	OCSM	|	U024C : 00 : 28		☐ ⚠️	Lost Communication with Seat Control Module 'H'
	PSCM	|	U3003 : 68 : 28		☐ ⚠️	Battery Voltage
	SCCM	|	U2101 : 00 : 28	SSM	☐ ⚠️	Control Module Configuration Incompatible

April 06, 2024

☐ Select All

Time : 06:24 AM
Odometer :
39281 mi

★	HCM	|	B1439 : 87 : 08		⚠	Right Levelling Actuator
★	HCM	|	B1D64 : 87 : 08		⚠	Left Headlamp Swiveling Motor
★	HCM	|	B1D65 : 87 : 08		⚠	Right Headlamp Swiveling Motor
★	OCSM	|	U024C : 00 : 28		⚠	Lost Communication with Seat Control Module 'H'
★	PSCM	|	U3003 : 68 : 28		⚠	Battery Voltage
	SCCM	|	U2101 : 00 : 28	SSM	⚠	Control Module Configuration Incompatible

April 05, 2024

☐ Select All

Time : 05:40 PM
Odometer :
39254 mi

| ★ | PSCM | \| | U3003 : 68 : 2E | | ⚠ | Battery Voltage |
| | SCCM | \| | U2101 : 00 : 28 | SSM | ⚠ | Control Module Configuration Incompatible |

April 03, 2024

☐ Select All

Time : 09:22 AM
Odometer :
39253 mi

| ★ | SCCM | \| | U2101 : 00 : 28 | SSM | ⚠ | Control Module Configuration Incompatible |

April 02, 2024

☐ Select All

Time : 12:24 PM
Odometer :
39252 mi

	SECM	|	U3003 : 68 : 08		⚠	Battery Voltage
	HCM	|	B1D64 : 87 : 08		⚠	Left Headlamp Swiveling Motor
	HCM	|	B1439 : 87 : 08		⚠	Right Levelling Actuator
	SASM	|	U3003 : 1C : 0A		⚠	Battery Voltage
	IPMA	|	U2400 : 00 : 28	TSB	⚠	Ethernet Failure With Gateway Module A (GWM)
	ABS	|	U3001 : 68 : 28	SSM	⚠	Control Module Improper Shutdown Performance
	PSCM	|	U3003 : 68 : 2E		⚠	Battery Voltage
	SECM	|	U3003 : 1C : 08		⚠	Battery Voltage
	HCM	|	B1437 : 87 : 08		⚠	Left Levelling Actuator
	HCM	|	B1041 : 54 : 0B		⚠	Levelling Control
	HCM	|	B1D65 : 87 : 08		⚠	Right Headlamp Swiveling Motor