Units ⚙

Connected Vehicle Status

Vin: 1FTFW1E13MFB77676

Last Vehicle Status Update: January 06, 2024 08:25 AM
*Note: Do not use as a pressure gauge

Diesel Exhaust Fluid

Exhaust Fluid Level: **11%**
Distance To Empty: **1600 Miles**

Oil Life Remaining

40%

Tire Pressure (PSI)*

34   34

34   32

32

Recommended Tire Pressure(cold)
Front : **35** | Rear : **35**

Fuel Level

F

E

Fuel Level: **13%**
Fuel Range: **93 Miles to empty**

Odometer

37139 Miles

60-Day VHA/DTC History

Last Vehicle Health Update: January 03, 2024 10:42 AM

January 2024

Sun	Mon	Tue	Wed	Thu	Fri	Sat
	1 ⚠️🟠	2	3 ⚠️ℹ️	4	5	6
7	8	9	10	11	12	13
14	15	16	17	18	19	20
21	22	23	24	25	26	27
28	29	30	31			

December 2023

Sun	Mon	Tue	Wed	Thu	Fri	Sat
3	4	5 ⚠️ℹ️	6	7 ⚠️ℹ️	8	9
10	11	12 ⚠️ℹ️	13 ⚠️	14 ⚠️	15	16
17 ⚠️	18	19 ⚠️	20 ⚠️	21 ⚠️	22	23
24 ⚠️	25	26 ⚠️ℹ️	27 ⚠️ℹ️	28	29 🟠	30 ⚠️ℹ️
31 🟠 ⚠️						

November 2023

Sun	Mon	Tue	Wed	Thu	Fri	Sat
5	6	7	1	2	3	4
12	13	14 ⚠️🟠	8	9	10	11
19	20	21	15	16	17	18
26	27	28	22	23	24	25
			29	30		

Vehicle Health Alerts (VHA) and Diagnostic Trouble Codes (DTC)

Date	Time	Odometer	Event Description	★	Module		DTC	: FT : SB	⇕ TSB/GSB/SSM		Send to Search	Description

Select All ☐

Time : 10:42 AM
Odometer :
37139 mi

Clear Alert - Washer Fluid Low

⚠	Invalid Data Received From Body Control Module	DSM	U0422 : 00 : 08
⚠	Left Headlamp Swiveling Motor	HCM	B1D64 : 87 : 08
⚠	Right Levelling Actuator	HCM	B1439 : 87 : 08
⚠	Right Headlamp Swiveling Motor	HCM	B1D65 : 87 : 08
⚠	Lost Communication with Seat Control Module 'H'	OCSM	U024C : 00 : 28
⚠	Battery Voltage	PSCM	U3003 : 68 : 2E ★
⚠	Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'	PSCM	U0415 : 00 : 28 TSB

Time : 09:09 AM
Odometer :
37128 mi

New Alert - Washer Fluid Low Show Details

⚠	Invalid Data Received From Body Control Module	DSM	U0422 : 00 : 08
⚠	Left Headlamp Swiveling Motor	HCM	B1D64 : 87 : 08
⚠	Right Levelling Actuator	HCM	B1439 : 87 : 08
⚠	Right Headlamp Swiveling Motor	HCM	B1D65 : 87 : 08
⚠	Lost Communication with Seat Control Module 'H'	OCSM	U024C : 00 : 28
⚠	Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'	PSCM	U0415 : 00 : 28 TSB

Time : 09:07 AM
Odometer :
37126 mi

Clear Alert - Washer Fluid Low

⚠	Invalid Data Received From Body Control Module	DSM	U0422 : 00 : 08 ★
⚠	Left Headlamp Swiveling Motor	HCM	B1D64 : 87 : 08
⚠	Right Levelling Actuator	HCM	B1439 : 87 : 08
⚠	Right Headlamp Swiveling Motor	HCM	B1D65 : 87 : 08
⚠	Lost Communication with Seat Control Module 'H'	OCSM	U024C : 00 : 28
⚠	Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'	PSCM	U0415 : 00 : 28 TSB

Time : 07:02 AM
Odometer :
37100 mi

New Alert - Washer Fluid Low Show Details

⚠	Left Headlamp Swiveling Motor	HCM	B1D64 : 87 : 08
⚠	Right Levelling Actuator	HCM	B1439 : 87 : 08
⚠	Right Headlamp Swiveling Motor	HCM	B1D65 : 87 : 08
⚠	Lost Communication with Seat Control Module 'H'	OCSM	U024C : 00 : 28
⚠	Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'	PSCM	U0415 : 00 : 28 TSB

Time : 07:00 AM
Odometer :
37098 mi

Clear Alert - Washer Fluid Low

⚠	Left Headlamp Swiveling Motor	HCM	B1D64 : 87 : 08
⚠	Right Levelling Actuator	HCM	B1439 : 87 : 08
⚠	Right Headlamp Swiveling Motor	HCM	B1D65 : 87 : 08

| OCSM | U024C : 00 : 28 | | Lost Communication with Seat Control Module 'H' |
| PSCM | U0415 : 00 : 28 | TSB | Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A' |

January 01, 2024

☐ Select All

Time : 03:47 PM
Odometer :
37028 mi

New Alert - Washer Fluid Low Show Details

☐ ⚠	HCM	B1D64 : 87 : 08		Left Headlamp Swiveling Motor
☐ ⚠	HCM	B1439 : 87 : 08		Right Levelling Actuator
☐ ⚠	HCM	B1D65 : 87 : 08		Right Headlamp Swiveling Motor
☐ ⚠	OCSM	U024C : 00 : 28		Lost Communication with Seat Control Module 'H'
☐ ⚠	PSCM	U0415 : 00 : 28	TSB	Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 03:46 PM
Odometer :
37026 mi

Clear Alert - Washer Fluid Low

☐ ⚠	HCM	B1D64 : 87 : 08		Left Headlamp Swiveling Motor
☐ ⚠	HCM	B1439 : 87 : 08		Right Levelling Actuator
☐ ⚠	HCM	B1D65 : 87 : 08		Right Headlamp Swiveling Motor
☐ ⚠	OCSM	U024C : 00 : 28		Lost Communication with Seat Control Module 'H'
☐ ⚠	PSCM	U0415 : 00 : 28	TSB	Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

☐

Time : 08:53 AM
Odometer :
36984 mi

New Alert - Washer Fluid Low Show Details

HCM	B1D64 : 87 : 08		⚠ ☐ Left Headlamp Swiveling Motor
HCM	B1439 : 87 : 08		⚠ ☐ Right Levelling Actuator
HCM	B1D65 : 87 : 08		⚠ ☐ Right Headlamp Swiveling Motor
OCSM	U024C : 00 : 28		⚠ ☐ Lost Communication with Seat Control Module 'H'
PSCM	U0415 : 00 : 28	TSB	⚠ ☐ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 08:49 AM
Odometer :
36983 mi

Clear Alert - Washer Fluid Low

HCM	B1D64 : 87 : 08		⚠ ☐ Left Headlamp Swiveling Motor
HCM	B1439 : 87 : 08		⚠ ☐ Right Levelling Actuator
HCM	B1D65 : 87 : 08		⚠ ☐ Right Headlamp Swiveling Motor
OCSM	U024C : 00 : 28		⚠ ☐ Lost Communication with Seat Control Module 'H'
PSCM	U0415 : 00 : 28	TSB	⚠ ☐ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 08:07 AM
Odometer :
36978 mi

New Alert - Washer Fluid Low Show Details

HCM	B1D64 : 87 : 08		⚠ ☐ Left Headlamp Swiveling Motor
HCM	B1439 : 87 : 08		⚠ ☐ Right Levelling Actuator
HCM	B1D65 : 87 : 08		⚠ ☐ Right Headlamp Swiveling Motor
OCSM	U024C : 00 : 28		⚠ ☐ Lost Communication with Seat Control Module 'H'
PSCM	U0415 : 00 : 28	TSB	⚠ ☐ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Select All

Time : 03:59 PM
Odometer :
36974 mi

Clear Alert - Washer Fluid Low

Module	Code	Description	
HCM	B1D64 : 87 : 08	⚠	Left Headlamp Swiveling Motor
HCM	B1439 : 87 : 08	⚠	Right Levelling Actuator
HCM	B1D65 : 87 : 08	⚠	Right Headlamp Swiveling Motor
OCSM	U024C : 00 : 28	⚠	Lost Communication with Seat Control Module 'H'
PSCM	U0415 : 00 : 28	TSB ⚠	Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 08:19 AM
Odometer :
36960 mi

New Alert - Washer Fluid Low Show Details

Module	Code	Description	
HCM	B1D64 : 87 : 08	⚠	Left Headlamp Swiveling Motor
HCM	B1439 : 87 : 08	⚠	Right Levelling Actuator
HCM	B1D65 : 87 : 08	⚠	Right Headlamp Swiveling Motor
OCSM	U024C : 00 : 28	⚠	Lost Communication with Seat Control Module 'H'
PSCM	U0415 : 00 : 28	TSB ⚠	Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 08:17 AM
Odometer :
36960 mi

Clear Alert - Washer Fluid Low

Module	Code	Description	
HCM	B1D64 : 87 : 08	⚠	Left Headlamp Swiveling Motor
HCM	B1439 : 87 : 08	⚠	Right Levelling Actuator
HCM	B1D65 : 87 : 08	⚠	Right Headlamp Swiveling Motor
OCSM	U024C : 00 : 28	⚠	Lost Communication with Seat Control Module 'H'
PSCM	U0415 : 00 : 28	TSB ⚠	Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 08:03 AM
Odometer :
36959 mi

New Alert - Washer Fluid Low Show Details

Module	Code	Description	
DSM	U0422 : 00 : 08	⚠	Invalid Data Received From Body Control Module
HCM	B1D64 : 87 : 08	⚠	Left Headlamp Swiveling Motor
HCM	B1439 : 87 : 08	⚠	Right Levelling Actuator
HCM	B1D65 : 87 : 08	⚠	Right Headlamp Swiveling Motor
OCSM	U024C : 00 : 28	⚠	Lost Communication with Seat Control Module 'H'
PSCM	U0415 : 00 : 28	TSB ⚠	Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 07:53 AM
Odometer :
36952 mi

Clear Alert - Washer Fluid Low

Module	Code	Description	
★ DSM	U0422 : 00 : 08	⚠	Invalid Data Received From Body Control Module
HCM	B1D64 : 87 : 08	⚠	Left Headlamp Swiveling Motor
HCM	B1439 : 87 : 08	⚠	Right Levelling Actuator
HCM	B1D65 : 87 : 08	⚠	Right Headlamp Swiveling Motor
OCSM	U024C : 00 : 28	⚠	Lost Communication with Seat Control Module 'H'

December 29, 2023

☐ Select All

Time : 04:02 PM
Odometer :
36916 mi

New Alert - Washer Fluid Low Show Details

☐	HCM	B1D64 : 87 : 08		⚠ Left Headlamp Swiveling Motor
☐	HCM	B1439 : 87 : 08		⚠ Right Levelling Actuator
☐	HCM	B1D65 : 87 : 08		⚠ Right Headlamp Swiveling Motor
☐	OCSM	U024C : 00 : 28		⚠ Lost Communication with Seat Control Module 'H'
☐	PSCM	U0415 : 00 : 2E	TSB	⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 04:00 PM
Odometer :
36915 mi

Clear Alert - Washer Fluid Low

☐	HCM	B1D64 : 87 : 08		⚠ Left Headlamp Swiveling Motor
☐	HCM	B1439 : 87 : 08		⚠ Right Levelling Actuator
☐	HCM	B1D65 : 87 : 08		⚠ Right Headlamp Swiveling Motor
☐	OCSM	U024C : 00 : 28		⚠ Lost Communication with Seat Control Module 'H'
☐	PSCM	U0415 : 00 : 2E	TSB	⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 07:07 AM
Odometer :
36893 mi

New Alert - Washer Fluid Low Show Details

☐	HCM	B1D64 : 87 : 08		⚠ Left Headlamp Swiveling Motor
☐	HCM	B1439 : 87 : 08		⚠ Right Levelling Actuator
☐	HCM	B1D65 : 87 : 08		⚠ Right Headlamp Swiveling Motor
☐	OCSM	U024C : 00 : 28		⚠ Lost Communication with Seat Control Module 'H'
☐	PSCM	U0415 : 00 : 2E	TSB	⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

December 27, 2023

☐ Select All

Time : 07:29 AM
Odometer : 36773 mi

Clear Alert - Washer Fluid Low

HCM	B1D64 : 87 : 08	⚠ Left Headlamp Swiveling Motor
HCM	B1439 : 87 : 08	⚠ Right Levelling Actuator
HCM	B1D65 : 87 : 08	⚠ Right Headlamp Swiveling Motor
OCSM	U024C : 00 : 28	⚠ Lost Communication with Seat Control Module 'H'
PSCM	U0415 : 00 : 2E — TSB	⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 07:14 AM
Odometer : 36762 mi

New Alert - Washer Fluid Low Show Details

HCM	B1D64 : 87 : 08	⚠ Left Headlamp Swiveling Motor
HCM	B1439 : 87 : 08	⚠ Right Levelling Actuator
HCM	B1D65 : 87 : 08	⚠ Right Headlamp Swiveling Motor
OCSM	U024C : 00 : 28	⚠ Lost Communication with Seat Control Module 'H'
PSCM	U0415 : 00 : 2E — TSB	⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 06:57 AM
Odometer : 36754 mi

HCM	B1D64 : 87 : 08	⚠ Left Headlamp Swiveling Motor
HCM	B1439 : 87 : 08	⚠ Right Levelling Actuator
HCM	B1D65 : 87 : 08	⚠ Right Headlamp Swiveling Motor
OCSM	U024C : 00 : 28	⚠ Lost Communication with Seat Control Module 'H'
★ PSCM	U0415 : 00 : 2E — TSB	⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

December 26, 2023

☐ Select All

Time : 07:33 AM
Odometer : 36708 mi

Clear Alert - Washer Fluid Low

HCM	B1D64 : 87 : 08	⚠ Left Headlamp Swiveling Motor
HCM	B1439 : 87 : 08	⚠ Right Levelling Actuator
HCM	B1D65 : 87 : 08	⚠ Right Headlamp Swiveling Motor
OCSM	U024C : 00 : 28	⚠ Lost Communication with Seat Control Module 'H'

Time : 07:29 AM
Odometer : 36708 mi

New Alert - Washer Fluid Low Show Details

HCM	B1D64 : 87 : 08	⚠ Left Headlamp Swiveling Motor
HCM	B1439 : 87 : 08	⚠ Right Levelling Actuator
HCM	B1D65 : 87 : 08	⚠ Right Headlamp Swiveling Motor
OCSM	U024C : 00 : 28	⚠ Lost Communication with Seat Control Module 'H'

Time : 12:19 PM
Odometer :
36674 mi

Select All

⚠	HCM	B1D64 : 87 : 08	Left Headlamp Swiveling Motor
⚠	HCM	B1439 : 87 : 08	Right Levelling Actuator
⚠	HCM	B1D65 : 87 : 08	Right Headlamp Swiveling Motor
⚠	OCSM	U024C : 00 : 28	Lost Communication with Seat Control Module 'H'

Time : 07:50 AM
Odometer :
36654 mi

★ ⚠	DSM	U0422 : 00 : 08	Invalid Data Received From Body Control Module
⚠	HCM	B1D64 : 87 : 08	Left Headlamp Swiveling Motor
⚠	HCM	B1439 : 87 : 08	Right Levelling Actuator
⚠	HCM	B1D65 : 87 : 08	Right Headlamp Swiveling Motor
⚠	OCSM	U024C : 00 : 28	Lost Communication with Seat Control Module 'H'

Time : 07:55 AM
Odometer :
36647 mi

Select All

⚠	HCM	B1D64 : 87 : 08	Left Headlamp Swiveling Motor
⚠	HCM	B1439 : 87 : 08	Right Levelling Actuator
⚠	HCM	B1D65 : 87 : 08	Right Headlamp Swiveling Motor
⚠	OCSM	U024C : 00 : 28	Lost Communication with Seat Control Module 'H'

Time : 05:40 AM
Odometer :
36437 mi

Select All

⚠	HCM	B1D64 : 87 : 08	Left Headlamp Swiveling Motor
⚠	HCM	B1439 : 87 : 08	Right Levelling Actuator
⚠	HCM	B1D65 : 87 : 08	Right Headlamp Swiveling Motor
⚠	OCSM	U024C : 00 : 28	Lost Communication with Seat Control Module 'H'
★ ⚠	PSCM	U3003 : 68 : 28	Battery Voltage

Time : 04:29 PM
Odometer :
36399 mi

★	⚠	DSM	U0422 : 00 : 08	Invalid Data Received From Body Control Module
	⚠	HCM	B1D64 : 87 : 08	Left Headlamp Swivelling Motor
	⚠	HCM	B1439 : 87 : 08	Right Levelling Actuator
	⚠	HCM	B14DC : 87 : 08	Right Headlamp Driver Control System
	⚠	HCM	B1D65 : 87 : 08	Right Headlamp Swivelling Motor
★	⚠	OCSM	U024C : 00 : 2A	Lost Communication with Seat Control Module 'H'
	⚠	PSCM	U3003 : 68 : 28	Battery Voltage

Time : 06:55 AM
Odometer :
36305 mi

⚠	HCM	B14DC : 87 : 08	Right Headlamp Driver Control System
⚠	HCM	B1D65 : 87 : 08	Right Headlamp Swivelling Motor
⚠	HCM	B1D64 : 87 : 08	Left Headlamp Swivelling Motor
⚠	HCM	B1439 : 87 : 08	Right Levelling Actuator
⚠	OCSM	U024C : 00 : 28	Lost Communication with Seat Control Module 'H'
⚠	PSCM	U3003 : 68 : 28	Battery Voltage

☐ Select All

Time : 12:17 PM
Odometer :
36229 mi

HCM	B1D64 : 87 : 08	⚠	Left Headlamp Swiveling Motor
HCM	B1439 : 87 : 08	⚠	Right Levelling Actuator
HCM	B14DC : 87 : 08	⚠	Right Headlamp Driver Control System
HCM	B1D65 : 87 : 08	⚠	Right Headlamp Swiveling Motor
IPMA	B115E : 31 : 28	⚠	Camera Module
OCSM	U024C : 00 : 28 SSM	⚠	Lost Communication with Seat Control Module 'H'
PSCM	U3003 : 68 : 28	⚠	Battery Voltage

Time : 11:55 AM
Odometer :
36227 mi

★ DSM	U0422 : 00 : 08	⚠	Invalid Data Received From Body Control Module
HCM	B1D64 : 87 : 08	⚠	Left Headlamp Swiveling Motor
HCM	B1439 : 87 : 08	⚠	Right Levelling Actuator
HCM	B14DC : 87 : 08	⚠	Right Headlamp Driver Control System
HCM	B1D65 : 87 : 08	⚠	Right Headlamp Swiveling Motor
IPMA	B115E : 31 : 28	⚠	Camera Module
OCSM	U024C : 00 : 28 SSM	⚠	Lost Communication with Seat Control Module 'H'
PSCM	U3003 : 68 : 28	⚠	Battery Voltage

Time : 08:59 AM
Odometer :
36210 mi

HCM	B1D64 : 87 : 08	⚠	Left Headlamp Swiveling Motor
HCM	B1439 : 87 : 08	⚠	Right Levelling Actuator
HCM	B14DC : 87 : 08	⚠	Right Headlamp Driver Control System
HCM	B1D65 : 87 : 08	⚠	Right Headlamp Swiveling Motor
IPMA	B115E : 31 : 28	⚠	Camera Module
OCSM	U024C : 00 : 28 SSM	⚠	Lost Communication with Seat Control Module 'H'
★ PSCM	U3003 : 68 : 28	⚠	Battery Voltage

December 14, 2023 (implied first column)

Time : 07:16 AM
Odometer :
36194 mi

	Module	Code	Description
★	DSM	U0422 : 00 : 08	Invalid Data Received From Body Control Module
	HCM	B1D64 : 87 : 08	Left Headlamp Swiveling Motor
	HCM	B1439 : 87 : 08	Right Levelling Actuator
	HCM	B14DC : 87 : 08	Right Headlamp Driver Control System
	HCM	B1D65 : 87 : 08	Right Headlamp Swiveling Motor
	IPMA	B115E : 31 : 28	Camera Module
	OCSM	U024C : 00 : 28	Lost Communication with Seat Control Module 'H' (SSM)
★	PSCM	U3003 : 68 : 2C	Battery Voltage

December 14, 2023

Time : 06:25 AM
Odometer :
36046 mi

☐ Select All

	Module	Code	Description
★	HCM	B1D64 : 87 : 08	Left Headlamp Swiveling Motor
★	HCM	B1439 : 87 : 08	Right Levelling Actuator
★	HCM	B14DC : 87 : 08	Right Headlamp Driver Control System
★	HCM	B1D65 : 87 : 08	Right Headlamp Swiveling Motor
	IPMA	B115E : 31 : 28	Camera Module
★	OCSM	U024C : 00 : 28	Lost Communication with Seat Control Module 'H' (SSM)
	PSCM	U3003 : 68 : 28	Battery Voltage

December 13, 2023

Time : 04:57 PM
Odometer :
36011 mi

☐ Select All

	Module	Code	Description
★	HCM	B1439 : 87 : 0A	Right Levelling Actuator
★	HCM	B1D65 : 87 : 0A	Right Headlamp Swiveling Motor
★	HCM	B1D64 : 87 : 0A	Left Headlamp Swiveling Motor
	IPMA	B115E : 31 : 28	Camera Module
★	OCSM	U024C : 00 : 2A	Lost Communication with Seat Control Module 'H' (SSM)
	PSCM	U3003 : 68 : 28	Battery Voltage

☐ Select All

Time : 07:19 PM
Odometer :
35982 mi

★	DSM	U0422 : 00 : 08	⚠	Invalid Data Received From Body Control Module
	HCM	B1D64 : 87 : 08	⚠	Left Headlamp Swiveling Motor
	HCM	B1439 : 87 : 08	⚠	Right Levelling Actuator
	HCM	B1D65 : 87 : 08	⚠	Right Headlamp Swiveling Motor
★	IPMA	B115E : 31 : 28	⚠	Camera Module
	OCSM	U024C : 00 : 28	SSM ⚠	Lost Communication with Seat Control Module 'H'
	PSCM	U3003 : 68 : 28	⚠	Battery Voltage

Time : 06:02 PM
Odometer :
35963 mi

★	HCM	B1D64 : 87 : 08	⚠	Left Headlamp Swiveling Motor
★	HCM	B1439 : 87 : 08	⚠	Right Levelling Actuator
★	HCM	B1D65 : 87 : 08	⚠	Right Headlamp Swiveling Motor
★	IPMA	B115E : 31 : 2C	⚠	Camera Module
★	OCSM	U024C : 00 : 28	SSM ⚠	Lost Communication with Seat Control Module 'H'
	PSCM	U3003 : 68 : 28	⚠	Battery Voltage

Time : 04:53 PM
Odometer :
35944 mi

★	HCM	B1439 : 87 : 0A	⚠	Right Levelling Actuator
★	HCM	B1D65 : 87 : 0A	⚠	Right Headlamp Swiveling Motor
★	HCM	B1D64 : 87 : 0A	⚠	Left Headlamp Swiveling Motor
★	OCSM	U024C : 00 : 2A	⚠	Lost Communication with Seat Control Module 'H'
★	PSCM	U3003 : 68 : 28	⚠	Battery Voltage

Time : 08:17 AM
Odometer :
35932 mi

★	HCM	B1D64 : 87 : 08	⚠	Left Headlamp Swiveling Motor
★	HCM	B1439 : 87 : 08	⚠	Right Levelling Actuator
★	HCM	B1D65 : 87 : 08	⚠	Right Headlamp Swiveling Motor
★	PSCM	U3003 : 68 : 2C	⚠	Battery Voltage

Time : 02:32 PM
Odometer :
35931 mi

PSCM | U3003 : 68 : 2E

☐ Select All

⚠ Battery Voltage

Time : 10:52 AM
Odometer :
35930 mi

Clear Alert - Service Engine Soon

HCM	B1D64 : 87 : 08	☐ ⚠ Left Headlamp Swiveling Motor
HCM	B1439 : 87 : 08	☐ ⚠ Right Levelling Actuator
HCM	B1437 : 01 : 08	☐ ⚠ Left Levelling Actuator
HCM	B1437 : 87 : 08	☐ ⚠ Left Levelling Actuator
HCM	B1D65 : 87 : 08	☐ ⚠ Right Headlamp Swiveling Motor
PSCM	U3003 : 68 : 2E	☐ ⚠ Battery Voltage

Time : 05:52 PM
Odometer :
35929 mi

New Alert - Service Engine Soon   Show Details

☐ Select All

HCM	B1D64 : 87 : 08		☐ ⚠ Left Headlamp Swiveling Motor
HCM	B1439 : 87 : 08		☐ ⚠ Right Levelling Actuator
HCM	B14DC : 87 : 08		☐ ⚠ Right Headlamp Driver Control System
HCM	B1437 : 01 : 08		☐ ⚠ Left Levelling Actuator
HCM	B1437 : 87 : 08		☐ ⚠ Left Levelling Actuator
HCM	B1D65 : 87 : 08		☐ ⚠ Right Headlamp Swiveling Motor
HCM	B14DB : 87 : 08		☐ ⚠ Left Headlamp Driver Control System
IPMA	U2400 : 00 : 2F		☐ ⚠ Ethernet Failure With Gateway Module A (GWM)
PCM	P00C7 : 00 : 24	TSB	☐ ⚠ Intake Air Pressure Measurement System - Multiple Sensor Correlation (Bank 1)
PCM	U060F : 00 : AC		☐ Lost Communication With Mass or Volume Air Flow Sensor 'A'
PSCM	U3003 : 68 : 2E		☐ ⚠ Battery Voltage
SASM	U3003 : 1C : 0A		☐ ⚠ Battery Voltage
SECM	U3003 : 68 : 08		☐ ⚠ Battery Voltage
SECM	U3003 : 1C : 08		☐ ⚠ Battery Voltage