

Last Vehicle Status Update: February 06, 2024 08:01 AM

*Note: Do not use as a pressure gauge

Refresh

Odometer



38446 Miles

Fuel Level



Fuel Level: 53%
Fuel Range: 337 Miles to empty

Tire Pressure (PSI)*



Recommended Tire Pressure(cold)
Front : 35 | Rear : 35

Oil Life Remaining



13%

Diesel Exhaust Fluid



Exhaust Fluid Level: 100%
Distance To Empty: 8500 Miles

60-Day VHA/DTC History

Last Vehicle Health Update: February 06, 2024 07:09 AM

December 2023

Sun	Mon	Tue	Wed	Thu
3	4	5	6	7
10	11			
	16			
		26	27	28
	31			

January 2024

Sun	Mon	Tue	Wed	Thu
		1	2	
			3	4
7	8		9	10
		16	17	
			24	25
28	29	30	31	

February 2024

Sun	Mon	Tue	Wed	Thu
				1
			7	8
11	12	13	14	15
18	19	20	21	22
25	26	27	28	29

Vehicle Health Alerts (VHA) and Diagnostic Trouble Codes (DTC)

February 06, 2024 Select All

<p>Time : 07:09 AM Odometer : 38418 mi</p>	<table border="0" style="width: 100%;"> <tr><td>HCM</td><td> </td><td>B14DC: 87 : 0A</td></tr> <tr><td>HCM</td><td> </td><td>B1439: 87 : 0A</td></tr> <tr><td>HCM</td><td> </td><td>B1D65: 87 : 0A</td></tr> <tr><td>OCSM</td><td> </td><td>U024C: 00 : 28</td></tr> <tr><td>HCM</td><td> </td><td>B1D64: 87 : 0A</td></tr> </table>	HCM		B14DC: 87 : 0A	HCM		B1439: 87 : 0A	HCM		B1D65: 87 : 0A	OCSM		U024C: 00 : 28	HCM		B1D64: 87 : 0A	<table border="0" style="width: 100%;"> <tr><td><input type="checkbox"/> ⚠</td><td>Right Headlamp Driver Control System</td></tr> <tr><td><input type="checkbox"/> ⚠</td><td>Right Levelling Actuator</td></tr> <tr><td><input type="checkbox"/> ⚠</td><td>Right Headlamp Swiveling Motor</td></tr> <tr><td><input type="checkbox"/> ⚠</td><td>Lost Communication with Seat Control Module 'H'</td></tr> <tr><td><input type="checkbox"/> ⚠</td><td>Left Headlamp Swiveling Motor</td></tr> </table>	<input type="checkbox"/> ⚠	Right Headlamp Driver Control System	<input type="checkbox"/> ⚠	Right Levelling Actuator	<input type="checkbox"/> ⚠	Right Headlamp Swiveling Motor	<input type="checkbox"/> ⚠	Lost Communication with Seat Control Module 'H'	<input type="checkbox"/> ⚠	Left Headlamp Swiveling Motor
HCM		B14DC: 87 : 0A																									
HCM		B1439: 87 : 0A																									
HCM		B1D65: 87 : 0A																									
OCSM		U024C: 00 : 28																									
HCM		B1D64: 87 : 0A																									
<input type="checkbox"/> ⚠	Right Headlamp Driver Control System																										
<input type="checkbox"/> ⚠	Right Levelling Actuator																										
<input type="checkbox"/> ⚠	Right Headlamp Swiveling Motor																										
<input type="checkbox"/> ⚠	Lost Communication with Seat Control Module 'H'																										
<input type="checkbox"/> ⚠	Left Headlamp Swiveling Motor																										

February 05, 2024 Select All

<p>Time : 04:36 PM Odometer : 38378 mi</p>	<table border="0" style="width: 100%;"> <tr><td>★ HCM</td><td> </td><td>B1D64: 87 : 0A</td></tr> <tr><td>★ HCM</td><td> </td><td>B1D65: 87 : 0A</td></tr> <tr><td>★ HCM</td><td> </td><td>B1439: 87 : 0A</td></tr> <tr><td>★ HCM</td><td> </td><td>B14DC: 87 : 0A</td></tr> <tr><td>OCSM</td><td> </td><td>U024C: 00 : 28</td></tr> </table>	★ HCM		B1D64: 87 : 0A	★ HCM		B1D65: 87 : 0A	★ HCM		B1439: 87 : 0A	★ HCM		B14DC: 87 : 0A	OCSM		U024C: 00 : 28	<table border="0" style="width: 100%;"> <tr><td><input type="checkbox"/> ⚠</td><td>Left Headlamp Swiveling Motor</td></tr> <tr><td><input type="checkbox"/> ⚠</td><td>Right Headlamp Swiveling Motor</td></tr> <tr><td><input type="checkbox"/> ⚠</td><td>Right Levelling Actuator</td></tr> <tr><td><input type="checkbox"/> ⚠</td><td>Right Headlamp Driver Control System</td></tr> <tr><td><input type="checkbox"/> ⚠</td><td>Lost Communication with Seat Control Module 'H'</td></tr> </table>	<input type="checkbox"/> ⚠	Left Headlamp Swiveling Motor	<input type="checkbox"/> ⚠	Right Headlamp Swiveling Motor	<input type="checkbox"/> ⚠	Right Levelling Actuator	<input type="checkbox"/> ⚠	Right Headlamp Driver Control System	<input type="checkbox"/> ⚠	Lost Communication with Seat Control Module 'H'
★ HCM		B1D64: 87 : 0A																									
★ HCM		B1D65: 87 : 0A																									
★ HCM		B1439: 87 : 0A																									
★ HCM		B14DC: 87 : 0A																									
OCSM		U024C: 00 : 28																									
<input type="checkbox"/> ⚠	Left Headlamp Swiveling Motor																										
<input type="checkbox"/> ⚠	Right Headlamp Swiveling Motor																										
<input type="checkbox"/> ⚠	Right Levelling Actuator																										
<input type="checkbox"/> ⚠	Right Headlamp Driver Control System																										
<input type="checkbox"/> ⚠	Lost Communication with Seat Control Module 'H'																										

February 04, 2024 Select All

<p>Time : 08:09 AM Odometer : 38328 mi</p>	<table border="0" style="width: 100%;"> <tr><td>★ HCM</td><td> </td><td>B1D65: 87 : 08</td></tr> <tr><td>★ HCM</td><td> </td><td>B1439: 87 : 08</td></tr> <tr><td>★ HCM</td><td> </td><td>B1D64: 87 : 08</td></tr> <tr><td>★ OCSM</td><td> </td><td>U024C: 00 : 28</td></tr> </table>	★ HCM		B1D65: 87 : 08	★ HCM		B1439: 87 : 08	★ HCM		B1D64: 87 : 08	★ OCSM		U024C: 00 : 28	<table border="0" style="width: 100%;"> <tr><td><input type="checkbox"/> ⚠</td><td>Right Headlamp Swiveling Motor</td></tr> <tr><td><input type="checkbox"/> ⚠</td><td>Right Levelling Actuator</td></tr> <tr><td><input type="checkbox"/> ⚠</td><td>Left Headlamp Swiveling Motor</td></tr> <tr><td><input type="checkbox"/> ⚠</td><td>Lost Communication with Seat Control Module 'H'</td></tr> </table>	<input type="checkbox"/> ⚠	Right Headlamp Swiveling Motor	<input type="checkbox"/> ⚠	Right Levelling Actuator	<input type="checkbox"/> ⚠	Left Headlamp Swiveling Motor	<input type="checkbox"/> ⚠	Lost Communication with Seat Control Module 'H'
★ HCM		B1D65: 87 : 08																				
★ HCM		B1439: 87 : 08																				
★ HCM		B1D64: 87 : 08																				
★ OCSM		U024C: 00 : 28																				
<input type="checkbox"/> ⚠	Right Headlamp Swiveling Motor																					
<input type="checkbox"/> ⚠	Right Levelling Actuator																					
<input type="checkbox"/> ⚠	Left Headlamp Swiveling Motor																					
<input type="checkbox"/> ⚠	Lost Communication with Seat Control Module 'H'																					

February 03, 2024

<p>Time : 08:37 AM Odometer : 38309 mi</p>		<p>⚠ No DTCs Present</p>
---	--	--------------------------

February 02, 2024

Select All

Time : 05:21 PM



OTA On-Vehicle
Activity-Update
Activation is
finished

Time : 05:16 PM



OTA On-Vehicle
Activity-Vehicle
Activation Start

Time : 05:03 PM

Odometer :
38272 mi

★	OCSM		U024C: 00 : 28
	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	HCM		B1437: 87 : 08
	HCM		B1D65: 87 : 08
	HCM		B14DB: 87 : 08

- ⚠ Lost Communication with Seat Control Module 'H'
- ⚠ Left Headlamp Swiveling Motor
- ⚠ Right Levelling Actuator
- ⚠ Left Levelling Actuator
- ⚠ Right Headlamp Swiveling Motor
- ⚠ Left Headlamp Driver Control System

January 29, 2024

Time : 07:37 AM



New Alert - Time to
Plan

Odometer :
38000 mi

January 26, 2024

Select All

Time : 06:24 AM

Odometer :
37832 mi

★	HCM		B14DB: 87 : 08
★	HCM		B1437: 87 : 08
★	HCM		B15A7: 87 : 08
★	OCSM		U024C: 00 : 2A
	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	HCM		B1D65: 87 : 08

- ⚠ Left Headlamp Driver Control System
- ⚠ Left Levelling Actuator
- ⚠ Left Matrix Controller Actuator
- ⚠ Lost Communication with Seat Control Module 'H'
- ⚠ Left Headlamp Swiveling Motor
- ⚠ Right Levelling Actuator
- ⚠ Right Headlamp Swiveling Motor

January 23, 2024

Select All

Time : 06:56 AM

Odometer :

37634 mi

★ HCM | B1D65: 87 : 08

★ HCM | B1439: 87 : 08

★ HCM | B1D64: 87 : 08

OCSM | U024C: 00 : 28

⚠ Right Headlamp Swiveling Motor

⚠ Right Levelling Actuator

⚠ Left Headlamp Swiveling Motor

⚠ Lost Communication with Seat Control Module 'H'

January 22, 2024

Select All

Time : 07:12 PM

Odometer :

37623 mi

OCSM | U024C: 00 : 28

⚠ Lost Communication with Seat Control Module 'H'

Time : 06:59 AM

Odometer :

37556 mi

★ HCM | B14DB: 87 : 08

★ HCM | B1D65: 87 : 08

★ HCM | B1437: 87 : 08

★ HCM | B1439: 87 : 08

★ HCM | B1D64: 87 : 08

★ OCSM | U024C: 00 : 28

⚠ Left Headlamp Driver Control System

⚠ Right Headlamp Swiveling Motor

⚠ Left Levelling Actuator

⚠ Right Levelling Actuator

⚠ Left Headlamp Swiveling Motor

⚠ Lost Communication with Seat Control Module 'H'

January 21, 2024

Select All

Time : 08:31 PM

Odometer :
37556 mi

★	PSCM		U023A: 00 : 2E
	HCM		B1437: 87 : 0B
	HCM		B14DB: 87 : 0B
	HCM		B1D64: 87 : 0B

<input type="checkbox"/>	⚠	Lost Communication With Image Processing Module A
<input type="checkbox"/>	⚠	Left Levelling Actuator
<input type="checkbox"/>	⚠	Left Headlamp Driver Control System
<input type="checkbox"/>	⚠	Left Headlamp Swiveling Motor

Time : 08:10 PM

Odometer :
37556 mi

	HCM		B1437: 87 : 0B
	HCM		B14DB: 87 : 0B
	HCM		B1D64: 87 : 0B

<input type="checkbox"/>	⚠	Left Levelling Actuator
<input type="checkbox"/>	⚠	Left Headlamp Driver Control System
<input type="checkbox"/>	⚠	Left Headlamp Swiveling Motor

Time : 07:43 PM

Odometer :
37556 mi

★	HCM		B1D64: 87 : 0B
★	HCM		B14DB: 87 : 0B
★	HCM		B1437: 87 : 0B
★	SCCM		U2101: 00 : 2A <small>SSM</small>

<input type="checkbox"/>	⚠	Left Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Left Headlamp Driver Control System
<input type="checkbox"/>	⚠	Left Levelling Actuator
<input type="checkbox"/>	⚠	Control Module Configuration Incompatible

Time : 11:24 AM

Odometer :
37545 mi

★	HCM		B14DB: 87 : 0B
★	HCM		B1437: 87 : 0B
★	HCM		B1D64: 87 : 0B

<input type="checkbox"/>	⚠	Left Headlamp Driver Control System
<input type="checkbox"/>	⚠	Left Levelling Actuator
<input type="checkbox"/>	⚠	Left Headlamp Swiveling Motor

Time : 09:26 AM

Odometer :
37544 mi

★	DSM		U0422: 00 : 08
★	HCM		B1D64: 87 : 0B
★	HCM		B14DB: 87 : 0B
★	HCM		B1437: 87 : 0B
	OCSM		U024C: 00 : 28

<input type="checkbox"/>	⚠	Invalid Data Received From Body Control Module
<input type="checkbox"/>	⚠	Left Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Left Headlamp Driver Control System
<input type="checkbox"/>	⚠	Left Levelling Actuator
<input type="checkbox"/>	⚠	Lost Communication with Seat Control Module 'H'

Time : 08:07 AM

Odometer :
37524 mi

★	OCSM		U024C: 00 : 28
---	-------------	--	-----------------------

<input type="checkbox"/>	⚠	Lost Communication with Seat Control Module 'H'
--------------------------	---	---

January 20, 2024

Time : 03:52 PM

Odometer :
37518 mi

⚠ No DTCs Present

January 19, 2024

Select All

Time : 05:09 PM

Odometer :
37482 mi

★	HCM		B1D64: 87 : 0A
★	HCM		B1D65: 87 : 0A
★	HCM		B1439: 87 : 0A
	OCSM		U024C: 00 : 28

<input type="checkbox"/>	⚠	Left Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Right Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Right Levelling Actuator
<input type="checkbox"/>	⚠	Lost Communication with Seat Control Module 'H'

Time : 07:06 AM

Odometer :
37453 mi

★	DSM		U0422: 00 : 08
	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	HCM		B1D65: 87 : 08
	OCSM		U024C: 00 : 28

<input type="checkbox"/>	⚠	Invalid Data Received From Body Control Module
<input type="checkbox"/>	⚠	Left Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Right Levelling Actuator
<input type="checkbox"/>	⚠	Right Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Lost Communication with Seat Control Module 'H'

January 18, 2024

Select All

Time : 04:14 PM

Odometer :
37415 mi

	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	HCM		B1D65: 87 : 08
	OCSM		U024C: 00 : 28

<input type="checkbox"/>	⚠	Left Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Right Levelling Actuator
<input type="checkbox"/>	⚠	Right Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Lost Communication with Seat Control Module 'H'

Time : 07:10 AM

Odometer :
37387 mi

	OCSM		U024C: 00 : 28
	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	DSM		U0422: 00 : 08
	HCM		B1D65: 87 : 08

<input type="checkbox"/>	⚠	Lost Communication with Seat Control Module 'H'
<input type="checkbox"/>	⚠	Left Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Right Levelling Actuator
<input type="checkbox"/>	⚠	Invalid Data Received From Body Control Module
<input type="checkbox"/>	⚠	Right Headlamp Swiveling Motor

January 15, 2024

Select All

Time : 06:53 AM

Odometer :
37266 mi

★	DSM		U0422: 00 : 08
★	PSCM		U3003: 68 : 2E
	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	HCM		B14DC: 87 : 08
	HCM		B1437: 87 : 08
	HCM		B1D65: 87 : 08
	HCM		B14DB: 87 : 08
	OCSM		U024C: 00 : 28

- ⚠ Invalid Data Received From Body Control Module
- ⚠ Battery Voltage
- ⚠ Left Headlamp Swiveling Motor
- ⚠ Right Levelling Actuator
- ⚠ Right Headlamp Driver Control System
- ⚠ Left Levelling Actuator
- ⚠ Right Headlamp Swiveling Motor
- ⚠ Left Headlamp Driver Control System
- ⚠ Lost Communication with Seat Control Module 'H'

January 14, 2024

Select All

Time : 12:26 PM

Odometer :
37249 mi

★	OCSM		U024C: 00 : 28
★	PSCM		U3003: 68 : 28
	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	HCM		B14DC: 87 : 08
	HCM		B1437: 87 : 08
	HCM		B1D65: 87 : 08
	HCM		B14DB: 87 : 08

- ⚠ Lost Communication with Seat Control Module 'H'
- ⚠ Battery Voltage
- ⚠ Left Headlamp Swiveling Motor
- ⚠ Right Levelling Actuator
- ⚠ Right Headlamp Driver Control System
- ⚠ Left Levelling Actuator
- ⚠ Right Headlamp Swiveling Motor
- ⚠ Left Headlamp Driver Control System

Time : 08:32 AM

Odometer :
37220 mi

★	DSM		U0422: 00 : 08
★	HCM		B1D65: 87 : 08
★	HCM		B1439: 87 : 08
★	PSCM		U3003: 68 : 2E
	HCM		B1D64: 87 : 08
	HCM		B14DC: 87 : 08
	HCM		B1437: 87 : 08
	HCM		B14DB: 87 : 08
	OCSM		U024C: 00 : 2A

- ⚠ Invalid Data Received From Body Control Module
- ⚠ Right Headlamp Swiveling Motor
- ⚠ Right Levelling Actuator
- ⚠ Battery Voltage
- ⚠ Left Headlamp Swiveling Motor
- ⚠ Right Headlamp Driver Control System
- ⚠ Left Levelling Actuator
- ⚠ Left Headlamp Driver Control System
- ⚠ Lost Communication with Seat Control Module 'H'

January 12, 2024

Select All

Time : 04:58 PM

Odometer :
37155 mi

★	HCM		B14DB: 87 : 08
★	HCM		B1D65: 87 : 0A
★	HCM		B1437: 87 : 08
★	HCM		B1439: 87 : 0A
★	HCM		B1D64: 87 : 08
★	OCSM		U024C: 00 : 2A
★	PSCM		U3003: 68 : 28
	HCM		B14DC: 87 : 08

<input type="checkbox"/>	⚠	Left Headlamp Driver Control System
<input type="checkbox"/>	⚠	Right Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Left Levelling Actuator
<input type="checkbox"/>	⚠	Right Levelling Actuator
<input type="checkbox"/>	⚠	Left Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Lost Communication with Seat Control Module 'H'
<input type="checkbox"/>	⚠	Battery Voltage
<input type="checkbox"/>	⚠	Right Headlamp Driver Control System

Time : 08:08 AM

Odometer :
37143 mi

★	HCM		B1D64: 87 : 0B
★	HCM		B14DB: 87 : 0B
★	HCM		B1437: 87 : 0B
★	PSCM		U3003: 68 : 2C
	HCM		B1439: 87 : 08
	HCM		B14DC: 87 : 08
	HCM		B1D65: 87 : 08

<input type="checkbox"/>	⚠	Left Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Left Headlamp Driver Control System
<input type="checkbox"/>	⚠	Left Levelling Actuator
<input type="checkbox"/>	⚠	Battery Voltage
<input type="checkbox"/>	⚠	Right Levelling Actuator
<input type="checkbox"/>	⚠	Right Headlamp Driver Control System
<input type="checkbox"/>	⚠	Right Headlamp Swiveling Motor

January 11, 2024

Select All

Time : 03:48 PM

Odometer :
37143 mi

★	HCM		B14DC: 87 : 08
	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	HCM		B1D65: 87 : 08

<input type="checkbox"/>	⚠	Right Headlamp Driver Control System
<input type="checkbox"/>	⚠	Left Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Right Levelling Actuator
<input type="checkbox"/>	⚠	Right Headlamp Swiveling Motor

January 09, 2024

Select All

Time : 10:23 AM

Odometer :
37141 mi



Clear Alert - Washer
Fluid Low

★	HCM		B1D65: 87 : 08
★	HCM		B1439: 87 : 08
★	HCM		B1D64: 87 : 08

<input type="checkbox"/>	⚠	Right Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Right Levelling Actuator
<input type="checkbox"/>	⚠	Left Headlamp Swiveling Motor

January 08, 2024

Time : 02:53 PM



New Alert - Washer [Show](#)

Odometer :

Fluid Low

[Details](#)

37139 mi



No DTCs Present

Time : 10:42 AM

Odometer :
37139 mi



Clear Alert - Washer
Fluid Low

★	PSCM		U3003: 68 : 2E
	DSM		U0422: 00 : 08
	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	HCM		B1D65: 87 : 08
	OCSM		U024C: 00 : 28
	PSCM		U0415: 00 : 28

TSB

- Battery Voltage
- Invalid Data Received From Body Control Module
- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Swiveling Motor
- Lost Communication with Seat Control Module 'H'
- Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 09:09 AM

Odometer :
37128 mi



New Alert - Washer [Show Details](#)
Fluid Low

	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	DSM		U0422: 00 : 08
	HCM		B1D65: 87 : 08
	OCSM		U024C: 00 : 28
	PSCM		U0415: 00 : 28

TSB

- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Invalid Data Received From Body Control Module
- Right Headlamp Swiveling Motor
- Lost Communication with Seat Control Module 'H'
- Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 09:07 AM

Odometer :
37126 mi



Clear Alert - Washer
Fluid Low

★	DSM		U0422: 00 : 08
	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	HCM		B1D65: 87 : 08
	OCSM		U024C: 00 : 28
	PSCM		U0415: 00 : 28

TSB

- Invalid Data Received From Body Control Module
- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Swiveling Motor
- Lost Communication with Seat Control Module 'H'
- Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 07:02 AM

Odometer :
37100 mi



New Alert - Washer [Show Details](#)
Fluid Low

	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	HCM		B1D65: 87 : 08
	OCSM		U024C: 00 : 28
	PSCM		U0415: 00 : 28

TSB

- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Swiveling Motor
- Lost Communication with Seat Control Module 'H'
- Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 07:00 AM

Odometer :
37098 mi





Clear Alert - Washer
Fluid Low

	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	HCM		B1D65: 87 : 08

- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Swiveling Motor

OCSM | U024C: 00 : 28
PSCM | U0415: 00 : 28

TSB

 Lost Communication with Seat Control Module 'H'
  Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

January 01, 2024

Select All






Time : 03:47 PM
Odometer :
37028 mi



New Alert - Washer Fluid Low [Show Details](#)

HCM | B1D64: 87 : 08
HCM | B1439: 87 : 08
HCM | B1D65: 87 : 08
OCSM | U024C: 00 : 28
PSCM | U0415: 00 : 28

TSB

 Left Headlamp Swiveling Motor
  Right Levelling Actuator
  Right Headlamp Swiveling Motor
  Lost Communication with Seat Control Module 'H'
  Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'






Time : 03:46 PM
Odometer :
37026 mi



Clear Alert - Washer Fluid Low

HCM | B1D64: 87 : 08
HCM | B1439: 87 : 08
HCM | B1D65: 87 : 08
OCSM | U024C: 00 : 28
PSCM | U0415: 00 : 28

TSB

 Left Headlamp Swiveling Motor
  Right Levelling Actuator
  Right Headlamp Swiveling Motor
  Lost Communication with Seat Control Module 'H'
  Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 08:53 AM



New Alert - Washer Fluid Low [Show Details](#)

Odometer :
36984 mi

HCM | B1D64: 87 : 08

HCM | B1439: 87 : 08

HCM | B1D65: 87 : 08

OCSM | U024C: 00 : 28

PSCM | U0415: 00 : 28 TSB

- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Swiveling Motor
- Lost Communication with Seat Control Module 'H'
- Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 08:49 AM



Clear Alert - Washer Fluid Low

Odometer :
36983 mi

HCM | B1D64: 87 : 08

HCM | B1439: 87 : 08

HCM | B1D65: 87 : 08

OCSM | U024C: 00 : 28

PSCM | U0415: 00 : 28 TSB

- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Swiveling Motor
- Lost Communication with Seat Control Module 'H'
- Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 08:07 AM



New Alert - Washer Fluid Low [Show Details](#)

Odometer :
36978 mi

HCM | B1D64: 87 : 08

HCM | B1439: 87 : 08

HCM | B1D65: 87 : 08

OCSM | U024C: 00 : 28

PSCM | U0415: 00 : 28 TSB

- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Swiveling Motor
- Lost Communication with Seat Control Module 'H'
- Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 03:59 PM
Odometer :
 36974 mi



Clear Alert - Washer
 Fluid Low

HCM | B1D64: 87 : 08
 HCM | B1439: 87 : 08
 HCM | B1D65: 87 : 08
 OCSM | U024C: 00 : 28
 PSCM | U0415: 00 : 28

TSB

- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Swiveling Motor
- Lost Communication with Seat Control Module 'H'
- Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 08:19 AM
Odometer :
 36960 mi



New Alert - Washer [Show Details](#)
 Fluid Low

HCM | B1D64: 87 : 08
 HCM | B1439: 87 : 08
 HCM | B1D65: 87 : 08
 OCSM | U024C: 00 : 28
 PSCM | U0415: 00 : 28

TSB

- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Swiveling Motor
- Lost Communication with Seat Control Module 'H'
- Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 08:17 AM
Odometer :
 36960 mi



Clear Alert - Washer
 Fluid Low

HCM | B1D64: 87 : 08
 HCM | B1439: 87 : 08
 HCM | B1D65: 87 : 08
 OCSM | U024C: 00 : 28
 PSCM | U0415: 00 : 28

TSB

- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Swiveling Motor
- Lost Communication with Seat Control Module 'H'
- Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 08:03 AM
Odometer :
 36959 mi



New Alert - Washer [Show Details](#)
 Fluid Low

HCM | B1D64: 87 : 08
 HCM | B1439: 87 : 08
 DSM | U0422: 00 : 08
 HCM | B1D65: 87 : 08
 OCSM | U024C: 00 : 28
 PSCM | U0415: 00 : 28

TSB

- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Invalid Data Received From Body Control Module
- Right Headlamp Swiveling Motor
- Lost Communication with Seat Control Module 'H'
- Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 07:53 AM
Odometer :
 36952 mi




Clear Alert - Washer
 Fluid Low

★ **DSM** | **U0422: 00 : 08**
 ★ PSCM | U0415: 00 : 28
 HCM | B1D64: 87 : 08
 HCM | B1439: 87 : 08
 HCM | B1D65: 87 : 08

TSB

- Invalid Data Received From Body Control Module
- Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Swiveling Motor

OCSM | U024C: 00 : 28

 Lost Communication with Seat Control Module 'H'

December 29, 2023






Select All

Time : 04:02 PM
Odometer :
36916 mi



New Alert - Washer [Show](#)
Fluid Low [Details](#)

HCM | B1D64: 87 : 08
HCM | B1439: 87 : 08
HCM | B1D65: 87 : 08
PSCM | U0415: 00 : 2E TSB
OCSM | U024C: 00 : 28






 Left Headlamp Swiveling Motor
  Right Levelling Actuator
  Right Headlamp Swiveling Motor
  Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
  Lost Communication with Seat Control Module 'H'

Time : 04:00 PM
Odometer :
36915 mi



Clear Alert - Washer
Fluid Low

HCM | B1D64: 87 : 08
HCM | B1439: 87 : 08
HCM | B1D65: 87 : 08
PSCM | U0415: 00 : 2E TSB
OCSM | U024C: 00 : 28






 Left Headlamp Swiveling Motor
  Right Levelling Actuator
  Right Headlamp Swiveling Motor
  Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
  Lost Communication with Seat Control Module 'H'

Time : 07:07 AM
Odometer :
36893 mi



New Alert - Washer [Show](#)
Fluid Low [Details](#)

HCM | B1D64: 87 : 08
HCM | B1439: 87 : 08
HCM | B1D65: 87 : 08
PSCM | U0415: 00 : 2E TSB
OCSM | U024C: 00 : 28

 Left Headlamp Swiveling Motor
  Right Levelling Actuator
  Right Headlamp Swiveling Motor
  Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
  Lost Communication with Seat Control Module 'H'

December 27, 2023

Select All

Time : 07:29 AM

Odometer :
36773 mi



Clear Alert - Washer
Fluid Low

HCM		B1D64: 87 : 08
HCM		B1439: 87 : 08
HCM		B1D65: 87 : 08
PSCM		U0415: 00 : 2E <small>TSB</small>
OCSM		U024C: 00 : 28

- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Swiveling Motor
- Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- Lost Communication with Seat Control Module 'H'

Time : 07:14 AM

Odometer :
36762 mi



New Alert - Washer [Show](#)
Fluid Low [Details](#)

HCM		B1D64: 87 : 08
HCM		B1439: 87 : 08
HCM		B1D65: 87 : 08
PSCM		U0415: 00 : 2E <small>TSB</small>
OCSM		U024C: 00 : 28

- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Swiveling Motor
- Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- Lost Communication with Seat Control Module 'H'

Time : 06:57 AM

Odometer :
36754 mi



PSCM		U0415: 00 : 2E <small>TSB</small>
HCM		B1D64: 87 : 08
HCM		B1439: 87 : 08
HCM		B1D65: 87 : 08
OCSM		U024C: 00 : 28

- Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Swiveling Motor
- Lost Communication with Seat Control Module 'H'

December 26, 2023

Select All

Time : 07:33 AM

Odometer :
36708 mi



Clear Alert - Washer
Fluid Low

HCM		B1D64: 87 : 08
HCM		B1439: 87 : 08
HCM		B1D65: 87 : 08
OCSM		U024C: 00 : 28

- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Swiveling Motor
- Lost Communication with Seat Control Module 'H'

Time : 07:29 AM

Odometer :
36708 mi



New Alert - Washer [Show](#)
Fluid Low [Details](#)

HCM		B1D64: 87 : 08
HCM		B1439: 87 : 08
HCM		B1D65: 87 : 08
OCSM		U024C: 00 : 28

- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Swiveling Motor
- Lost Communication with Seat Control Module 'H'

December 25, 2023

Select All

Time : 12:19 PM

Odometer :
36674 mi

HCM		B1D64: 87 : 08
HCM		B1439: 87 : 08
HCM		B1D65: 87 : 08
OCSM		U024C: 00 : 28

<input type="checkbox"/>		Left Headlamp Swiveling Motor
<input type="checkbox"/>		Right Levelling Actuator
<input type="checkbox"/>		Right Headlamp Swiveling Motor
<input type="checkbox"/>		Lost Communication with Seat Control Module 'H'

Time : 07:50 AM

Odometer :
36654 mi

★ DSM		U0422: 00 : 08
HCM		B1D64: 87 : 08
HCM		B1439: 87 : 08
HCM		B1D65: 87 : 08
OCSM		U024C: 00 : 28

<input type="checkbox"/>		Invalid Data Received From Body Control Module
<input type="checkbox"/>		Left Headlamp Swiveling Motor
<input type="checkbox"/>		Right Levelling Actuator
<input type="checkbox"/>		Right Headlamp Swiveling Motor
<input type="checkbox"/>		Lost Communication with Seat Control Module 'H'

December 24, 2023

Select All

Time : 07:55 AM

Odometer :
36647 mi

HCM		B1D64: 87 : 08
HCM		B1439: 87 : 08
HCM		B1D65: 87 : 08
OCSM		U024C: 00 : 28

<input type="checkbox"/>		Left Headlamp Swiveling Motor
<input type="checkbox"/>		Right Levelling Actuator
<input type="checkbox"/>		Right Headlamp Swiveling Motor
<input type="checkbox"/>		Lost Communication with Seat Control Module 'H'

December 21, 2023

Select All

Time : 05:40 AM

Odometer :
36437 mi

★ OCSM		U024C: 00 : 28
HCM		B1D64: 87 : 08
HCM		B1439: 87 : 08
HCM		B1D65: 87 : 08
PSCM		U3003: 68 : 28

<input type="checkbox"/>		Lost Communication with Seat Control Module 'H'
<input type="checkbox"/>		Left Headlamp Swiveling Motor
<input type="checkbox"/>		Right Levelling Actuator
<input type="checkbox"/>		Right Headlamp Swiveling Motor
<input type="checkbox"/>		Battery Voltage

December 20, 2023

Select All

Time : 04:29 PM

Odometer :
36399 mi

★	DSM		U0422: 00 : 08
★	OCSM		U024C: 00 : 2A
	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	HCM		B14DC: 87 : 08
	HCM		B1D65: 87 : 08
	PSCM		U3003: 68 : 28

- ⚠ Invalid Data Received From Body Control Module
- ⚠ Lost Communication with Seat Control Module 'H'
- ⚠ Left Headlamp Swiveling Motor
- ⚠ Right Levelling Actuator
- ⚠ Right Headlamp Driver Control System
- ⚠ Right Headlamp Swiveling Motor
- ⚠ Battery Voltage

December 19, 2023

Select All

Time : 06:55 AM

Odometer :
36305 mi

	HCM		B14DC: 87 : 08
	HCM		B1D65: 87 : 08
	OCSM		U024C: 00 : 28
	HCM		B1D64: 87 : 08
	PSCM		U3003: 68 : 28
	HCM		B1439: 87 : 08

- ⚠ Right Headlamp Driver Control System
- ⚠ Right Headlamp Swiveling Motor
- ⚠ Lost Communication with Seat Control Module 'H'
- ⚠ Left Headlamp Swiveling Motor
- ⚠ Battery Voltage
- ⚠ Right Levelling Actuator

Time : 12:17 PMOdometer :
36229 mi

IPMA		B115E: 31 : 28	SSM / SSM
HCM		B1D64: 87 : 08	
PSCM		U3003: 68 : 28	
HCM		B1439: 87 : 08	
HCM		B14DC: 87 : 08	
HCM		B1D65: 87 : 08	
OCSM		U024C: 00 : 28	

-  Camera Module
-  Left Headlamp Swiveling Motor
-  Battery Voltage
-  Right Levelling Actuator
-  Right Headlamp Driver Control System
-  Right Headlamp Swiveling Motor
-  Lost Communication with Seat Control Module 'H'




Time : 11:55 AMOdometer :
36227 mi

★ DSM		U0422: 00 : 08	
HCM		B1D64: 87 : 08	
HCM		B1439: 87 : 08	
HCM		B14DC: 87 : 08	
HCM		B1D65: 87 : 08	
IPMA		B115E: 31 : 28	SSM / SSM
OCSM		U024C: 00 : 28	
PSCM		U3003: 68 : 28	

-  Invalid Data Received From Body Control Module
-  Left Headlamp Swiveling Motor
-  Right Levelling Actuator
-  Right Headlamp Driver Control System
-  Right Headlamp Swiveling Motor
-  Camera Module
-  Lost Communication with Seat Control Module 'H'
-  Battery Voltage

Time : 08:59 AMOdometer :
36210 mi

★ PSCM		U3003: 68 : 28	
HCM		B1D64: 87 : 08	
HCM		B1439: 87 : 08	
HCM		B14DC: 87 : 08	
HCM		B1D65: 87 : 08	
IPMA		B115E: 31 : 28	SSM / SSM
OCSM		U024C: 00 : 28	

-  Battery Voltage
-  Left Headlamp Swiveling Motor
-  Right Levelling Actuator
-  Right Headlamp Driver Control System
-  Right Headlamp Swiveling Motor
-  Camera Module
-  Lost Communication with Seat Control Module 'H'

Time : 07:16 AM

Odometer :

36194 mi

★	DSM		U0422: 00 : 08
★	PSCM		U3003: 68 : 2C
	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	HCM		B14DC: 87 : 08
	HCM		B1D65: 87 : 08
	IPMA		B115E: 31 : 28
	OCSM		U024C: 00 : 28

SSM / SSM

- ⚠ Invalid Data Received From Body Control Module
- ⚠ Battery Voltage
- ⚠ Left Headlamp Swiveling Motor
- ⚠ Right Levelling Actuator
- ⚠ Right Headlamp Driver Control System
- ⚠ Right Headlamp Swiveling Motor
- ⚠ Camera Module
- ⚠ Lost Communication with Seat Control Module 'H'

December 14, 2023

Time : 06:25 AM

Odometer :

36046 mi

★	HCM		B1D65: 87 : 08
★	HCM		B14DC: 87 : 08
★	HCM		B1439: 87 : 08
★	HCM		B1D64: 87 : 08
★	OCSM		U024C: 00 : 28
	IPMA		B115E: 31 : 28
	PSCM		U3003: 68 : 28

SSM / SSM

- Select All
- ⚠ Right Headlamp Swiveling Motor
 - ⚠ Right Headlamp Driver Control System
 - ⚠ Right Levelling Actuator
 - ⚠ Left Headlamp Swiveling Motor
 - ⚠ Lost Communication with Seat Control Module 'H'
 - ⚠ Camera Module
 - ⚠ Battery Voltage

December 13, 2023

Time : 04:57 PM

Odometer :

36011 mi

★	HCM		B1D64: 87 : 0A
★	HCM		B1D65: 87 : 0A
★	HCM		B1439: 87 : 0A
★	OCSM		U024C: 00 : 2A
	IPMA		B115E: 31 : 28
	PSCM		U3003: 68 : 28








SSM / SSM

- Select All
- ⚠ Left Headlamp Swiveling Motor
 - ⚠ Right Headlamp Swiveling Motor
 - ⚠ Right Levelling Actuator
 - ⚠ Lost Communication with Seat Control Module 'H'
 - ⚠ Camera Module
 - ⚠ Battery Voltage

Time : 07:19 PMOdometer :
35982 mi

★	DSM		U0422: 00 : 08
★	IPMA		B115E: 31 : 28
	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	HCM		B1D65: 87 : 08
	OCSM		U024C: 00 : 28
	PSCM		U3003: 68 : 28







SSM / SSM

-  Invalid Data Received From Body Control Module
-  Camera Module
-  Left Headlamp Swiveling Motor
-  Right Levelling Actuator
-  Right Headlamp Swiveling Motor
-  Lost Communication with Seat Control Module 'H'
-  Battery Voltage

Time : 06:02 PMOdometer :
35963 mi






★	HCM		B1D65: 87 : 08
★	HCM		B1439: 87 : 08
★	HCM		B1D64: 87 : 08
★	IPMA		B115E: 31 : 2C
★	OCSM		U024C: 00 : 28
	PSCM		U3003: 68 : 28

SSM / SSM

-  Right Headlamp Swiveling Motor
-  Right Levelling Actuator
-  Left Headlamp Swiveling Motor
-  Camera Module
-  Lost Communication with Seat Control Module 'H'
-  Battery Voltage





Time : 04:53 PMOdometer :
35944 mi

★	HCM		B1D64: 87 : 0A
★	HCM		B1D65: 87 : 0A
★	HCM		B1439: 87 : 0A
★	OCSM		U024C: 00 : 2A
★	PSCM		U3003: 68 : 28

-  Left Headlamp Swiveling Motor
-  Right Headlamp Swiveling Motor
-  Right Levelling Actuator
-  Lost Communication with Seat Control Module 'H'
-  Battery Voltage

Time : 08:17 AMOdometer :
35932 mi

★	HCM		B1D65: 87 : 08
★	HCM		B1439: 87 : 08
★	HCM		B1D64: 87 : 08
★	PSCM		U3003: 68 : 2C

-  Right Headlamp Swiveling Motor
-  Right Levelling Actuator
-  Left Headlamp Swiveling Motor
-  Battery Voltage