

Last Vehicle Status Update: February 14, 2024 12:16 PM

\*Note: Do not use as a pressure gauge

Refresh

### Odometer



39170 Miles

### Fuel Level



Fuel Level: 27%  
Fuel Range: 179 Miles to empty

### Tire Pressure (PSI)\*



Recommended Tire Pressure(cold)  
Front : 35 | Rear : 35

### Oil Life Remaining



2%

### Diesel Exhaust Fluid



Exhaust Fluid Level: 94%  
Distance To Empty: 6000 Miles

### 60-Day VHA/DTC History

Last Vehicle Health Update: February 14, 2024 11:59 AM

#### December 2023

Sun	Mon	Tue	Wed	Thu
3	4	5	6	7
10	11	12	13	14
	18			
				28
	31			

#### January 2024

Sun	Mon	Tue	Wed	Thu
		2		4
7	8		10	
		16	17	
			25	
28	29	30		

#### February 2024

Sun	Mon	Tue	Wed	Thu
				1
		6	7	8
18	19	20	21	22
25	26	27	28	29

## Vehicle Health Alerts (VHA) and Diagnostic Trouble Codes (DTC)

**February 14, 2024**  Select All

<p><b>Time :</b> 11:59 AM Odometer : 39159 mi</p>	<table border="0" style="width: 100%;"> <tr><td>HCM</td><td> </td><td>B1439: 87 : 08</td></tr> <tr><td>IPMA</td><td> </td><td>U0565: 82 : 2C</td></tr> <tr><td>HCM</td><td> </td><td>B1D65: 87 : 08</td></tr> <tr><td>HCM</td><td> </td><td>B1437: 87 : 0B</td></tr> <tr><td>OCSM</td><td> </td><td>U024C: 00 : 28</td></tr> <tr><td>HCM</td><td> </td><td>B14DB: 87 : 0B</td></tr> <tr><td>HCM</td><td> </td><td>B1D64: 87 : 0B</td></tr> </table>	HCM		B1439: 87 : 08	IPMA		U0565: 82 : 2C	HCM		B1D65: 87 : 08	HCM		B1437: 87 : 0B	OCSM		U024C: 00 : 28	HCM		B14DB: 87 : 0B	HCM		B1D64: 87 : 0B	<table border="0" style="width: 100%;"> <tr><td><input type="checkbox"/> ⚠</td><td>Right Levelling Actuator</td></tr> <tr><td><input type="checkbox"/> ⚠</td><td>Invalid Data Received From Camera Module-Rear</td></tr> <tr><td><input type="checkbox"/> ⚠</td><td>Right Headlamp Swiveling Motor</td></tr> <tr><td><input type="checkbox"/> ⚠</td><td>Left Levelling Actuator</td></tr> <tr><td><input type="checkbox"/> ⚠</td><td>Lost Communication with Seat Control Module 'H'</td></tr> <tr><td><input type="checkbox"/> ⚠</td><td>Left Headlamp Driver Control System</td></tr> <tr><td><input type="checkbox"/> ⚠</td><td>Left Headlamp Swiveling Motor</td></tr> </table>	<input type="checkbox"/> ⚠	Right Levelling Actuator	<input type="checkbox"/> ⚠	Invalid Data Received From Camera Module-Rear	<input type="checkbox"/> ⚠	Right Headlamp Swiveling Motor	<input type="checkbox"/> ⚠	Left Levelling Actuator	<input type="checkbox"/> ⚠	Lost Communication with Seat Control Module 'H'	<input type="checkbox"/> ⚠	Left Headlamp Driver Control System	<input type="checkbox"/> ⚠	Left Headlamp Swiveling Motor
HCM		B1439: 87 : 08																																			
IPMA		U0565: 82 : 2C																																			
HCM		B1D65: 87 : 08																																			
HCM		B1437: 87 : 0B																																			
OCSM		U024C: 00 : 28																																			
HCM		B14DB: 87 : 0B																																			
HCM		B1D64: 87 : 0B																																			
<input type="checkbox"/> ⚠	Right Levelling Actuator																																				
<input type="checkbox"/> ⚠	Invalid Data Received From Camera Module-Rear																																				
<input type="checkbox"/> ⚠	Right Headlamp Swiveling Motor																																				
<input type="checkbox"/> ⚠	Left Levelling Actuator																																				
<input type="checkbox"/> ⚠	Lost Communication with Seat Control Module 'H'																																				
<input type="checkbox"/> ⚠	Left Headlamp Driver Control System																																				
<input type="checkbox"/> ⚠	Left Headlamp Swiveling Motor																																				

**February 13, 2024**  Select All

<p><b>Time :</b> 03:39 PM Odometer : 39027 mi</p>	<table border="0" style="width: 100%;"> <tr><td>★ HCM</td><td> </td><td>B1D64: 87 : 0B</td></tr> <tr><td>★ HCM</td><td> </td><td>B14DB: 87 : 0B</td></tr> <tr><td>★ HCM</td><td> </td><td>B1437: 87 : 0B</td></tr> <tr><td>★ IPMA</td><td> </td><td>U0565: 82 : 2C</td></tr> <tr><td>HCM</td><td> </td><td>B1439: 87 : 08</td></tr> <tr><td>HCM</td><td> </td><td>B1D65: 87 : 08</td></tr> <tr><td>OCSM</td><td> </td><td>U024C: 00 : 28</td></tr> </table>	★ HCM		B1D64: 87 : 0B	★ HCM		B14DB: 87 : 0B	★ HCM		B1437: 87 : 0B	★ IPMA		U0565: 82 : 2C	HCM		B1439: 87 : 08	HCM		B1D65: 87 : 08	OCSM		U024C: 00 : 28	<table border="0" style="width: 100%;"> <tr><td><input type="checkbox"/> ⚠</td><td>Left Headlamp Swiveling Motor</td></tr> <tr><td><input type="checkbox"/> ⚠</td><td>Left Headlamp Driver Control System</td></tr> <tr><td><input type="checkbox"/> ⚠</td><td>Left Levelling Actuator</td></tr> <tr><td><input type="checkbox"/> ⚠</td><td>Invalid Data Received From Camera Module-Rear</td></tr> <tr><td><input type="checkbox"/> ⚠</td><td>Right Levelling Actuator</td></tr> <tr><td><input type="checkbox"/> ⚠</td><td>Right Headlamp Swiveling Motor</td></tr> <tr><td><input type="checkbox"/> ⚠</td><td>Lost Communication with Seat Control Module 'H'</td></tr> </table>	<input type="checkbox"/> ⚠	Left Headlamp Swiveling Motor	<input type="checkbox"/> ⚠	Left Headlamp Driver Control System	<input type="checkbox"/> ⚠	Left Levelling Actuator	<input type="checkbox"/> ⚠	Invalid Data Received From Camera Module-Rear	<input type="checkbox"/> ⚠	Right Levelling Actuator	<input type="checkbox"/> ⚠	Right Headlamp Swiveling Motor	<input type="checkbox"/> ⚠	Lost Communication with Seat Control Module 'H'
★ HCM		B1D64: 87 : 0B																																			
★ HCM		B14DB: 87 : 0B																																			
★ HCM		B1437: 87 : 0B																																			
★ IPMA		U0565: 82 : 2C																																			
HCM		B1439: 87 : 08																																			
HCM		B1D65: 87 : 08																																			
OCSM		U024C: 00 : 28																																			
<input type="checkbox"/> ⚠	Left Headlamp Swiveling Motor																																				
<input type="checkbox"/> ⚠	Left Headlamp Driver Control System																																				
<input type="checkbox"/> ⚠	Left Levelling Actuator																																				
<input type="checkbox"/> ⚠	Invalid Data Received From Camera Module-Rear																																				
<input type="checkbox"/> ⚠	Right Levelling Actuator																																				
<input type="checkbox"/> ⚠	Right Headlamp Swiveling Motor																																				
<input type="checkbox"/> ⚠	Lost Communication with Seat Control Module 'H'																																				

**February 12, 2024**  Select All

<p><b>Time :</b> 09:23 PM Odometer : 38917 mi</p>	<p> <b>New Alert - Change Engine Oil Soon</b></p>																																				
<p><b>Time :</b> 06:42 AM Odometer : 38799 mi</p>	<table border="0" style="width: 100%;"> <tr><td>★ HCM</td><td> </td><td>B14DB: 87 : 08</td></tr> <tr><td>★ HCM</td><td> </td><td>B1D65: 87 : 08</td></tr> <tr><td>★ HCM</td><td> </td><td>B1437: 87 : 08</td></tr> <tr><td>★ HCM</td><td> </td><td>B14DC: 87 : 08</td></tr> <tr><td>★ HCM</td><td> </td><td>B1439: 87 : 08</td></tr> <tr><td>★ HCM</td><td> </td><td>B1D64: 87 : 08</td></tr> <tr><td>OCSM</td><td> </td><td>U024C: 00 : 28</td></tr> </table>	★ HCM		B14DB: 87 : 08	★ HCM		B1D65: 87 : 08	★ HCM		B1437: 87 : 08	★ HCM		B14DC: 87 : 08	★ HCM		B1439: 87 : 08	★ HCM		B1D64: 87 : 08	OCSM		U024C: 00 : 28	<table border="0" style="width: 100%;"> <tr><td><input type="checkbox"/> ⚠</td><td>Left Headlamp Driver Control System</td></tr> <tr><td><input type="checkbox"/> ⚠</td><td>Right Headlamp Swiveling Motor</td></tr> <tr><td><input type="checkbox"/> ⚠</td><td>Left Levelling Actuator</td></tr> <tr><td><input type="checkbox"/> ⚠</td><td>Right Headlamp Driver Control System</td></tr> <tr><td><input type="checkbox"/> ⚠</td><td>Right Levelling Actuator</td></tr> <tr><td><input type="checkbox"/> ⚠</td><td>Left Headlamp Swiveling Motor</td></tr> <tr><td><input type="checkbox"/> ⚠</td><td>Lost Communication with Seat Control Module 'H'</td></tr> </table>	<input type="checkbox"/> ⚠	Left Headlamp Driver Control System	<input type="checkbox"/> ⚠	Right Headlamp Swiveling Motor	<input type="checkbox"/> ⚠	Left Levelling Actuator	<input type="checkbox"/> ⚠	Right Headlamp Driver Control System	<input type="checkbox"/> ⚠	Right Levelling Actuator	<input type="checkbox"/> ⚠	Left Headlamp Swiveling Motor	<input type="checkbox"/> ⚠	Lost Communication with Seat Control Module 'H'
★ HCM		B14DB: 87 : 08																																			
★ HCM		B1D65: 87 : 08																																			
★ HCM		B1437: 87 : 08																																			
★ HCM		B14DC: 87 : 08																																			
★ HCM		B1439: 87 : 08																																			
★ HCM		B1D64: 87 : 08																																			
OCSM		U024C: 00 : 28																																			
<input type="checkbox"/> ⚠	Left Headlamp Driver Control System																																				
<input type="checkbox"/> ⚠	Right Headlamp Swiveling Motor																																				
<input type="checkbox"/> ⚠	Left Levelling Actuator																																				
<input type="checkbox"/> ⚠	Right Headlamp Driver Control System																																				
<input type="checkbox"/> ⚠	Right Levelling Actuator																																				
<input type="checkbox"/> ⚠	Left Headlamp Swiveling Motor																																				
<input type="checkbox"/> ⚠	Lost Communication with Seat Control Module 'H'																																				

February 11, 2024

Select All

Time : 11:37 AM

Odometer :  
38746 mi



Clear Alert - Washer  
Fluid Low

HCM		B14DC : 87 : 0A
HCM		B1439 : 87 : 0A
HCM		B1D65 : 87 : 0A
OCSM		U024C : 00 : 28
HCM		B1D64 : 87 : 0A

- Right Headlamp Driver Control System
- Right Levelling Actuator
- Right Headlamp Swiveling Motor
- Lost Communication with Seat Control Module 'H'
- Left Headlamp Swiveling Motor

Time : 10:14 AM

Odometer :  
38738 mi



New Alert - Washer [Show](#)  
Fluid Low [Details](#)

HCM		B14DC : 87 : 0A
HCM		B1439 : 87 : 0A
HCM		B1D65 : 87 : 0A
OCSM		U024C : 00 : 28
HCM		B1D64 : 87 : 0A

- Right Headlamp Driver Control System
- Right Levelling Actuator
- Right Headlamp Swiveling Motor
- Lost Communication with Seat Control Module 'H'
- Left Headlamp Swiveling Motor

February 05, 2024

Select All

Time : 04:36 PM

Odometer :  
38378 mi

★ HCM		B1D64 : 87 : 0A
★ HCM		B1D65 : 87 : 0A
★ HCM		B1439 : 87 : 0A
★ HCM		<b>B14DC : 87 : 0A</b>
OCSM		U024C : 00 : 28

- Left Headlamp Swiveling Motor
- Right Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Driver Control System
- Lost Communication with Seat Control Module 'H'

February 04, 2024

Select All

Time : 08:09 AM

Odometer :  
38328 mi

★ HCM		<b>B1D65 : 87 : 08</b>
★ HCM		<b>B1439 : 87 : 08</b>
★ HCM		<b>B1D64 : 87 : 08</b>
★ OCSM		<b>U024C : 00 : 28</b>

- Right Headlamp Swiveling Motor
- Right Levelling Actuator
- Left Headlamp Swiveling Motor
- Lost Communication with Seat Control Module 'H'

February 03, 2024

Time : 08:37 AM

Odometer :  
38309 mi

No DTCs Present

February 02, 2024

Select All

Time : 05:21 PM



OTA On-Vehicle  
Activity-Update  
Activation is  
finished

Time : 05:16 PM



OTA On-Vehicle  
Activity-Vehicle  
Activation Start

Time : 05:03 PM

Odometer :  
38272 mi

★	OCSM		U024C: 00 : 28
	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	HCM		B1437: 87 : 08
	HCM		B1D65: 87 : 08
	HCM		B14DB: 87 : 08

- Lost Communication with Seat Control Module 'H'
- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Left Levelling Actuator
- Right Headlamp Swiveling Motor
- Left Headlamp Driver Control System

January 29, 2024

Time : 07:37 AM



New Alert - Time to  
Plan

Odometer :  
38000 mi

January 26, 2024

Select All

Time : 06:24 AM

Odometer :  
37832 mi

★	HCM		B14DB: 87 : 08
★	HCM		B1437: 87 : 08
★	HCM		B15A7: 87 : 08
★	OCSM		U024C: 00 : 2A
	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	HCM		B1D65: 87 : 08

- Left Headlamp Driver Control System
- Left Levelling Actuator
- Left Matrix Controller Actuator
- Lost Communication with Seat Control Module 'H'
- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Swiveling Motor

January 23, 2024

Select All

Time : 06:56 AM

Odometer :

37634 mi

★	HCM		B1D65: 87 : 08
★	HCM		B1439: 87 : 08
★	HCM		B1D64: 87 : 08
	OCSM		U024C: 00 : 28

<input type="checkbox"/>	⚠	Right Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Right Levelling Actuator
<input type="checkbox"/>	⚠	Left Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Lost Communication with Seat Control Module 'H'

January 22, 2024

Select All

Time : 07:12 PM

Odometer :

37623 mi

	OCSM		U024C: 00 : 28
--	------	--	----------------

<input type="checkbox"/>	⚠	Lost Communication with Seat Control Module 'H'
--------------------------	---	---

Time : 06:59 AM

Odometer :

37556 mi

★	HCM		B14DB: 87 : 08
★	HCM		B1D65: 87 : 08
★	HCM		B1437: 87 : 08
★	HCM		B1439: 87 : 08
★	HCM		B1D64: 87 : 08
★	OCSM		U024C: 00 : 28

<input type="checkbox"/>	⚠	Left Headlamp Driver Control System
<input type="checkbox"/>	⚠	Right Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Left Levelling Actuator
<input type="checkbox"/>	⚠	Right Levelling Actuator
<input type="checkbox"/>	⚠	Left Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Lost Communication with Seat Control Module 'H'

January 21, 2024

Select All

Time : 08:31 PM

Odometer :  
37556 mi

★	<b>PSCM</b>		<b>U023A: 00 : 2E</b>
	HCM		B1437: 87 : 0B
	HCM		B14DB: 87 : 0B
	HCM		B1D64: 87 : 0B

<input type="checkbox"/>	⚠	Lost Communication With Image Processing Module A
<input type="checkbox"/>	⚠	Left Levelling Actuator
<input type="checkbox"/>	⚠	Left Headlamp Driver Control System
<input type="checkbox"/>	⚠	Left Headlamp Swiveling Motor

Time : 08:10 PM

Odometer :  
37556 mi

	HCM		B1437: 87 : 0B
	HCM		B14DB: 87 : 0B
	HCM		B1D64: 87 : 0B

<input type="checkbox"/>	⚠	Left Levelling Actuator
<input type="checkbox"/>	⚠	Left Headlamp Driver Control System
<input type="checkbox"/>	⚠	Left Headlamp Swiveling Motor

Time : 07:43 PM

Odometer :  
37556 mi

★	HCM		B1D64: 87 : 0B
★	HCM		B14DB: 87 : 0B
★	HCM		B1437: 87 : 0B
★	<b>SCCM</b>		<b>U2101: 00 : 2A</b> <small>SSM</small>

<input type="checkbox"/>	⚠	Left Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Left Headlamp Driver Control System
<input type="checkbox"/>	⚠	Left Levelling Actuator
<input type="checkbox"/>	⚠	Control Module Configuration Incompatible

Time : 11:24 AM

Odometer :  
37545 mi

★	HCM		B14DB: 87 : 0B
★	HCM		B1437: 87 : 0B
★	HCM		B1D64: 87 : 0B

<input type="checkbox"/>	⚠	Left Headlamp Driver Control System
<input type="checkbox"/>	⚠	Left Levelling Actuator
<input type="checkbox"/>	⚠	Left Headlamp Swiveling Motor

Time : 09:26 AM

Odometer :  
37544 mi

★	<b>DSM</b>		<b>U0422: 00 : 08</b>
★	<b>HCM</b>		<b>B1D64: 87 : 0B</b>
★	<b>HCM</b>		<b>B14DB: 87 : 0B</b>
★	<b>HCM</b>		<b>B1437: 87 : 0B</b>
	OCSM		U024C: 00 : 28

<input type="checkbox"/>	⚠	Invalid Data Received From Body Control Module
<input type="checkbox"/>	⚠	Left Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Left Headlamp Driver Control System
<input type="checkbox"/>	⚠	Left Levelling Actuator
<input type="checkbox"/>	⚠	Lost Communication with Seat Control Module 'H'

Time : 08:07 AM

Odometer :  
37524 mi

★	<b>OCSM</b>		<b>U024C: 00 : 28</b>
---	-------------	--	-----------------------

<input type="checkbox"/>	⚠	Lost Communication with Seat Control Module 'H'
--------------------------	---	---

January 20, 2024

Time : 03:52 PM

Odometer :  
37518 mi

⚠ No DTCs Present

January 19, 2024

Select All

Time : 05:09 PM

Odometer :  
37482 mi

★	HCM		B1D64: 87 : 0A
★	HCM		B1D65: 87 : 0A
★	HCM		B1439: 87 : 0A
	OCSM		U024C: 00 : 28

<input type="checkbox"/>	⚠	Left Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Right Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Right Levelling Actuator
<input type="checkbox"/>	⚠	Lost Communication with Seat Control Module 'H'

Time : 07:06 AM

Odometer :  
37453 mi

★	DSM		U0422: 00 : 08
	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	HCM		B1D65: 87 : 08
	OCSM		U024C: 00 : 28

<input type="checkbox"/>	⚠	Invalid Data Received From Body Control Module
<input type="checkbox"/>	⚠	Left Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Right Levelling Actuator
<input type="checkbox"/>	⚠	Right Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Lost Communication with Seat Control Module 'H'

January 18, 2024

Select All

Time : 04:14 PM

Odometer :  
37415 mi

	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	HCM		B1D65: 87 : 08
	OCSM		U024C: 00 : 28

<input type="checkbox"/>	⚠	Left Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Right Levelling Actuator
<input type="checkbox"/>	⚠	Right Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Lost Communication with Seat Control Module 'H'

Time : 07:10 AM

Odometer :  
37387 mi

	OCSM		U024C: 00 : 28
	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	DSM		U0422: 00 : 08
	HCM		B1D65: 87 : 08

<input type="checkbox"/>	⚠	Lost Communication with Seat Control Module 'H'
<input type="checkbox"/>	⚠	Left Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Right Levelling Actuator
<input type="checkbox"/>	⚠	Invalid Data Received From Body Control Module
<input type="checkbox"/>	⚠	Right Headlamp Swiveling Motor

January 15, 2024

Select All

Time : 06:53 AM

Odometer :  
37266 mi

★	DSM		U0422: 00 : 08
★	PSCM		U3003: 68 : 2E
	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	HCM		B14DC: 87 : 08
	HCM		B1437: 87 : 08
	HCM		B1D65: 87 : 08
	HCM		B14DB: 87 : 08
	OCSM		U024C: 00 : 28

- ⚠ Invalid Data Received From Body Control Module
- ⚠ Battery Voltage
- ⚠ Left Headlamp Swiveling Motor
- ⚠ Right Levelling Actuator
- ⚠ Right Headlamp Driver Control System
- ⚠ Left Levelling Actuator
- ⚠ Right Headlamp Swiveling Motor
- ⚠ Left Headlamp Driver Control System
- ⚠ Lost Communication with Seat Control Module 'H'

January 14, 2024

Select All

Time : 12:26 PM

Odometer :  
37249 mi

★	OCSM		U024C: 00 : 28
★	PSCM		U3003: 68 : 28
	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	HCM		B14DC: 87 : 08
	HCM		B1437: 87 : 08
	HCM		B1D65: 87 : 08
	HCM		B14DB: 87 : 08

- ⚠ Lost Communication with Seat Control Module 'H'
- ⚠ Battery Voltage
- ⚠ Left Headlamp Swiveling Motor
- ⚠ Right Levelling Actuator
- ⚠ Right Headlamp Driver Control System
- ⚠ Left Levelling Actuator
- ⚠ Right Headlamp Swiveling Motor
- ⚠ Left Headlamp Driver Control System

Time : 08:32 AM

Odometer :  
37220 mi

★	DSM		U0422: 00 : 08
★	HCM		B1D65: 87 : 08
★	HCM		B1439: 87 : 08
★	PSCM		U3003: 68 : 2E
	HCM		B1D64: 87 : 08
	HCM		B14DC: 87 : 08
	HCM		B1437: 87 : 08
	HCM		B14DB: 87 : 08
	OCSM		U024C: 00 : 2A

- ⚠ Invalid Data Received From Body Control Module
- ⚠ Right Headlamp Swiveling Motor
- ⚠ Right Levelling Actuator
- ⚠ Battery Voltage
- ⚠ Left Headlamp Swiveling Motor
- ⚠ Right Headlamp Driver Control System
- ⚠ Left Levelling Actuator
- ⚠ Left Headlamp Driver Control System
- ⚠ Lost Communication with Seat Control Module 'H'

January 12, 2024

Select All

Time : 04:58 PM

Odometer :  
37155 mi

★	HCM		B14DB: 87 : 08
★	HCM		B1D65: 87 : 0A
★	HCM		B1437: 87 : 08
★	HCM		B1439: 87 : 0A
★	HCM		B1D64: 87 : 08
★	<b>OCSM</b>		<b>U024C: 00 : 2A</b>
★	PSCM		U3003: 68 : 28
	HCM		B14DC: 87 : 08

<input type="checkbox"/>	⚠	Left Headlamp Driver Control System
<input type="checkbox"/>	⚠	Right Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Left Levelling Actuator
<input type="checkbox"/>	⚠	Right Levelling Actuator
<input type="checkbox"/>	⚠	Left Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Lost Communication with Seat Control Module 'H'
<input type="checkbox"/>	⚠	Battery Voltage
<input type="checkbox"/>	⚠	Right Headlamp Driver Control System

Time : 08:08 AM

Odometer :  
37143 mi

★	HCM		B1D64: 87 : 0B
★	<b>HCM</b>		<b>B14DB: 87 : 0B</b>
★	<b>HCM</b>		<b>B1437: 87 : 0B</b>
★	<b>PSCM</b>		<b>U3003: 68 : 2C</b>
	HCM		B1439: 87 : 08
	HCM		B14DC: 87 : 08
	HCM		B1D65: 87 : 08

<input type="checkbox"/>	⚠	Left Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Left Headlamp Driver Control System
<input type="checkbox"/>	⚠	Left Levelling Actuator
<input type="checkbox"/>	⚠	Battery Voltage
<input type="checkbox"/>	⚠	Right Levelling Actuator
<input type="checkbox"/>	⚠	Right Headlamp Driver Control System
<input type="checkbox"/>	⚠	Right Headlamp Swiveling Motor

January 11, 2024

Select All

Time : 03:48 PM

Odometer :  
37143 mi

★	<b>HCM</b>		<b>B14DC: 87 : 08</b>
	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	HCM		B1D65: 87 : 08

<input type="checkbox"/>	⚠	Right Headlamp Driver Control System
<input type="checkbox"/>	⚠	Left Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Right Levelling Actuator
<input type="checkbox"/>	⚠	Right Headlamp Swiveling Motor

January 09, 2024

Select All

Time : 10:23 AM

Odometer :  
37141 mi



Clear Alert - Washer  
Fluid Low

★	<b>HCM</b>		<b>B1D65: 87 : 08</b>
★	<b>HCM</b>		<b>B1439: 87 : 08</b>
★	<b>HCM</b>		<b>B1D64: 87 : 08</b>

<input type="checkbox"/>	⚠	Right Headlamp Swiveling Motor
<input type="checkbox"/>	⚠	Right Levelling Actuator
<input type="checkbox"/>	⚠	Left Headlamp Swiveling Motor

January 08, 2024

Time : 02:53 PM



New Alert - Washer [Show](#)

Odometer :

Fluid Low

[Details](#)

37139 mi



No DTCs Present

Time : 10:42 AM

Odometer :  
37139 mi



Clear Alert - Washer  
Fluid Low

★ PSCM		U3003: 68 : 2E
DSM		U0422: 00 : 08
HCM		B1D64: 87 : 08
HCM		B1439: 87 : 08
HCM		B1D65: 87 : 08
OCSM		U024C: 00 : 28
PSCM		U0415: 00 : 28

TSB

- ⚠ Battery Voltage
- ⚠ Invalid Data Received From Body Control Module
- ⚠ Left Headlamp Swiveling Motor
- ⚠ Right Levelling Actuator
- ⚠ Right Headlamp Swiveling Motor
- ⚠ Lost Communication with Seat Control Module 'H'
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 09:09 AM

Odometer :  
37128 mi



New Alert - Washer [Show Details](#)  
Fluid Low

HCM		B1D64: 87 : 08
HCM		B1439: 87 : 08
DSM		U0422: 00 : 08
HCM		B1D65: 87 : 08
OCSM		U024C: 00 : 28
PSCM		U0415: 00 : 28

TSB

- ⚠ Left Headlamp Swiveling Motor
- ⚠ Right Levelling Actuator
- ⚠ Invalid Data Received From Body Control Module
- ⚠ Right Headlamp Swiveling Motor
- ⚠ Lost Communication with Seat Control Module 'H'
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 09:07 AM

Odometer :  
37126 mi



Clear Alert - Washer  
Fluid Low

★ DSM		U0422: 00 : 08
HCM		B1D64: 87 : 08
HCM		B1439: 87 : 08
HCM		B1D65: 87 : 08
OCSM		U024C: 00 : 28
PSCM		U0415: 00 : 28

TSB

- ⚠ Invalid Data Received From Body Control Module
- ⚠ Left Headlamp Swiveling Motor
- ⚠ Right Levelling Actuator
- ⚠ Right Headlamp Swiveling Motor
- ⚠ Lost Communication with Seat Control Module 'H'
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 07:02 AM

Odometer :  
37100 mi



New Alert - Washer [Show Details](#)  
Fluid Low

HCM		B1D64: 87 : 08
HCM		B1439: 87 : 08
HCM		B1D65: 87 : 08
OCSM		U024C: 00 : 28
PSCM		U0415: 00 : 28

TSB

- ⚠ Left Headlamp Swiveling Motor
- ⚠ Right Levelling Actuator
- ⚠ Right Headlamp Swiveling Motor
- ⚠ Lost Communication with Seat Control Module 'H'
- ⚠ Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 07:00 AM

Odometer :  
37098 mi





Clear Alert - Washer  
Fluid Low

HCM		B1D64: 87 : 08
HCM		B1439: 87 : 08
HCM		B1D65: 87 : 08

- ⚠ Left Headlamp Swiveling Motor
- ⚠ Right Levelling Actuator
- ⚠ Right Headlamp Swiveling Motor

OCSM | U024C: 00 : 28

PSCM | U0415: 00 : 28 TSB

-  Lost Communication with Seat Control Module 'H'
-  Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

January 01, 2024

**Select All**

**Time :** 03:47 PM

Odometer :

37028 mi



New Alert - Washer [Show](#)  
Fluid Low [Details](#)






HCM | B1D64: 87 : 08

HCM | B1439: 87 : 08

HCM | B1D65: 87 : 08

OCSM | U024C: 00 : 28

PSCM | U0415: 00 : 28 TSB

-  Left Headlamp Swiveling Motor
-  Right Levelling Actuator
-  Right Headlamp Swiveling Motor
-  Lost Communication with Seat Control Module 'H'
-  Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

**Time :** 03:46 PM

Odometer :

37026 mi



Clear Alert - Washer  
Fluid Low






HCM | B1D64: 87 : 08

HCM | B1439: 87 : 08

HCM | B1D65: 87 : 08

OCSM | U024C: 00 : 28

PSCM | U0415: 00 : 28 TSB

-  Left Headlamp Swiveling Motor
-  Right Levelling Actuator
-  Right Headlamp Swiveling Motor
-  Lost Communication with Seat Control Module 'H'
-  Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 08:53 AM



New Alert - Washer Fluid Low [Show Details](#)

Odometer : 36984 mi

HCM		B1D64: 87 : 08
HCM		B1439: 87 : 08
HCM		B1D65: 87 : 08
OCSM		U024C: 00 : 28
PSCM		U0415: 00 : 28

TSB

- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Swiveling Motor
- Lost Communication with Seat Control Module 'H'
- Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 08:49 AM



Clear Alert - Washer Fluid Low

Odometer : 36983 mi

HCM		B1D64: 87 : 08
HCM		B1439: 87 : 08
HCM		B1D65: 87 : 08
OCSM		U024C: 00 : 28
PSCM		U0415: 00 : 28

TSB

- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Swiveling Motor
- Lost Communication with Seat Control Module 'H'
- Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 08:07 AM



New Alert - Washer Fluid Low [Show Details](#)

Odometer : 36978 mi

HCM		B1D64: 87 : 08
HCM		B1439: 87 : 08
HCM		B1D65: 87 : 08
OCSM		U024C: 00 : 28
PSCM		U0415: 00 : 28

TSB

- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Swiveling Motor
- Lost Communication with Seat Control Module 'H'
- Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

**Time :** 03:59 PM  
**Odometer :**  
 36974 mi



Clear Alert - Washer  
 Fluid Low

HCM | B1D64: 87 : 08  
 HCM | B1439: 87 : 08  
 HCM | B1D65: 87 : 08  
 OCSM | U024C: 00 : 28  
 PSCM | U0415: 00 : 28

TSB

- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Swiveling Motor
- Lost Communication with Seat Control Module 'H'
- Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

**Time :** 08:19 AM  
**Odometer :**  
 36960 mi



New Alert - Washer [Show Details](#)  
 Fluid Low

HCM | B1D64: 87 : 08  
 HCM | B1439: 87 : 08  
 HCM | B1D65: 87 : 08  
 OCSM | U024C: 00 : 28  
 PSCM | U0415: 00 : 28

TSB

- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Swiveling Motor
- Lost Communication with Seat Control Module 'H'
- Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

**Time :** 08:17 AM  
**Odometer :**  
 36960 mi



Clear Alert - Washer  
 Fluid Low

HCM | B1D64: 87 : 08  
 HCM | B1439: 87 : 08  
 HCM | B1D65: 87 : 08  
 OCSM | U024C: 00 : 28  
 PSCM | U0415: 00 : 28

TSB

- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Swiveling Motor
- Lost Communication with Seat Control Module 'H'
- Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

**Time :** 08:03 AM  
**Odometer :**  
 36959 mi



New Alert - Washer [Show Details](#)  
 Fluid Low

HCM | B1D64: 87 : 08  
 HCM | B1439: 87 : 08  
 DSM | U0422: 00 : 08  
 HCM | B1D65: 87 : 08  
 OCSM | U024C: 00 : 28  
 PSCM | U0415: 00 : 28

TSB

- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Invalid Data Received From Body Control Module
- Right Headlamp Swiveling Motor
- Lost Communication with Seat Control Module 'H'
- Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

**Time :** 07:53 AM  
**Odometer :**  
 36952 mi




Clear Alert - Washer  
 Fluid Low

★ **DSM** | **U0422: 00 : 08**  
 ★ PSCM | U0415: 00 : 28  
 HCM | B1D64: 87 : 08  
 HCM | B1439: 87 : 08  
 HCM | B1D65: 87 : 08

TSB

- Invalid Data Received From Body Control Module
- Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Swiveling Motor

OCSM | U024C: 00 : 28

 Lost Communication with Seat Control Module 'H'

December 29, 2023






**Select All**

**Time :** 04:02 PM  
**Odometer :**  
36916 mi



New Alert - Washer [Show](#)  
Fluid Low [Details](#)

HCM | B1D64: 87 : 08  
HCM | B1439: 87 : 08  
HCM | B1D65: 87 : 08  
PSCM | U0415: 00 : 2E [TSB](#)  
OCSM | U024C: 00 : 28






 Left Headlamp Swiveling Motor  
  Right Levelling Actuator  
  Right Headlamp Swiveling Motor  
  Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'  
  Lost Communication with Seat Control Module 'H'

**Time :** 04:00 PM  
**Odometer :**  
36915 mi



Clear Alert - Washer  
Fluid Low

HCM | B1D64: 87 : 08  
HCM | B1439: 87 : 08  
HCM | B1D65: 87 : 08  
PSCM | U0415: 00 : 2E [TSB](#)  
OCSM | U024C: 00 : 28






 Left Headlamp Swiveling Motor  
  Right Levelling Actuator  
  Right Headlamp Swiveling Motor  
  Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'  
  Lost Communication with Seat Control Module 'H'

**Time :** 07:07 AM  
**Odometer :**  
36893 mi



New Alert - Washer [Show](#)  
Fluid Low [Details](#)

HCM | B1D64: 87 : 08  
HCM | B1439: 87 : 08  
HCM | B1D65: 87 : 08  
PSCM | U0415: 00 : 2E [TSB](#)  
OCSM | U024C: 00 : 28

 Left Headlamp Swiveling Motor  
  Right Levelling Actuator  
  Right Headlamp Swiveling Motor  
  Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'  
  Lost Communication with Seat Control Module 'H'

December 27, 2023

Select All

Time : 07:29 AM

Odometer :  
36773 mi



Clear Alert - Washer  
Fluid Low

HCM		B1D64: 87 : 08
HCM		B1439: 87 : 08
HCM		B1D65: 87 : 08
PSCM		U0415: 00 : 2E <small>TSB</small>
OCSM		U024C: 00 : 28

- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Swiveling Motor
- Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- Lost Communication with Seat Control Module 'H'

Time : 07:14 AM

Odometer :  
36762 mi



New Alert - Washer [Show](#)  
Fluid Low [Details](#)

HCM		B1D64: 87 : 08
HCM		B1439: 87 : 08
HCM		B1D65: 87 : 08
PSCM		U0415: 00 : 2E <small>TSB</small>
OCSM		U024C: 00 : 28

- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Swiveling Motor
- Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- Lost Communication with Seat Control Module 'H'

Time : 06:57 AM

Odometer :  
36754 mi



<b>PSCM</b>		<b>U0415: 00 : 2E</b> <small>TSB</small>
HCM		B1D64: 87 : 08
HCM		B1439: 87 : 08
HCM		B1D65: 87 : 08
OCSM		U024C: 00 : 28

- Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'
- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Swiveling Motor
- Lost Communication with Seat Control Module 'H'

December 26, 2023

Select All

Time : 07:33 AM

Odometer :  
36708 mi



Clear Alert - Washer  
Fluid Low

HCM		B1D64: 87 : 08
HCM		B1439: 87 : 08
HCM		B1D65: 87 : 08
OCSM		U024C: 00 : 28

- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Swiveling Motor
- Lost Communication with Seat Control Module 'H'

Time : 07:29 AM

Odometer :  
36708 mi



New Alert - Washer [Show](#)  
Fluid Low [Details](#)

HCM		B1D64: 87 : 08
HCM		B1439: 87 : 08
HCM		B1D65: 87 : 08
OCSM		U024C: 00 : 28

- Left Headlamp Swiveling Motor
- Right Levelling Actuator
- Right Headlamp Swiveling Motor
- Lost Communication with Seat Control Module 'H'

December 25, 2023

Select All

Time : 12:19 PM

Odometer :  
36674 mi

HCM		B1D64: 87 : 08
HCM		B1439: 87 : 08
HCM		B1D65: 87 : 08
OCSM		U024C: 00 : 28

<input type="checkbox"/>		Left Headlamp Swiveling Motor
<input type="checkbox"/>		Right Levelling Actuator
<input type="checkbox"/>		Right Headlamp Swiveling Motor
<input type="checkbox"/>		Lost Communication with Seat Control Module 'H'

Time : 07:50 AM

Odometer :  
36654 mi

★ DSM		U0422: 00 : 08
HCM		B1D64: 87 : 08
HCM		B1439: 87 : 08
HCM		B1D65: 87 : 08
OCSM		U024C: 00 : 28

<input type="checkbox"/>		Invalid Data Received From Body Control Module
<input type="checkbox"/>		Left Headlamp Swiveling Motor
<input type="checkbox"/>		Right Levelling Actuator
<input type="checkbox"/>		Right Headlamp Swiveling Motor
<input type="checkbox"/>		Lost Communication with Seat Control Module 'H'

December 24, 2023

Select All

Time : 07:55 AM

Odometer :  
36647 mi

HCM		B1D64: 87 : 08
HCM		B1439: 87 : 08
HCM		B1D65: 87 : 08
OCSM		U024C: 00 : 28

<input type="checkbox"/>		Left Headlamp Swiveling Motor
<input type="checkbox"/>		Right Levelling Actuator
<input type="checkbox"/>		Right Headlamp Swiveling Motor
<input type="checkbox"/>		Lost Communication with Seat Control Module 'H'

December 21, 2023

Select All

Time : 05:40 AM

Odometer :  
36437 mi

★ OCSM		U024C: 00 : 28
HCM		B1D64: 87 : 08
HCM		B1439: 87 : 08
HCM		B1D65: 87 : 08
PSCM		U3003: 68 : 28

<input type="checkbox"/>		Lost Communication with Seat Control Module 'H'
<input type="checkbox"/>		Left Headlamp Swiveling Motor
<input type="checkbox"/>		Right Levelling Actuator
<input type="checkbox"/>		Right Headlamp Swiveling Motor
<input type="checkbox"/>		Battery Voltage

December 20, 2023

Select All

Time : 04:29 PM

Odometer :  
36399 mi

★	DSM		U0422: 00 : 08
★	OCSM		U024C: 00 : 2A
	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	HCM		B14DC: 87 : 08
	HCM		B1D65: 87 : 08
	PSCM		U3003: 68 : 28

- ⚠ Invalid Data Received From Body Control Module
- ⚠ Lost Communication with Seat Control Module 'H'
- ⚠ Left Headlamp Swiveling Motor
- ⚠ Right Levelling Actuator
- ⚠ Right Headlamp Driver Control System
- ⚠ Right Headlamp Swiveling Motor
- ⚠ Battery Voltage

December 19, 2023

Select All

Time : 06:55 AM

Odometer :  
36305 mi

	HCM		B14DC: 87 : 08
	HCM		B1D65: 87 : 08
	OCSM		U024C: 00 : 28
	HCM		B1D64: 87 : 08
	PSCM		U3003: 68 : 28
	HCM		B1439: 87 : 08

- ⚠ Right Headlamp Driver Control System
- ⚠ Right Headlamp Swiveling Motor
- ⚠ Lost Communication with Seat Control Module 'H'
- ⚠ Left Headlamp Swiveling Motor
- ⚠ Battery Voltage
- ⚠ Right Levelling Actuator

**Time :** 12:17 PM

Odometer :  
36229 mi

IPMA		B115E: 31 : 28	SSM / SSM
HCM		B1D64: 87 : 08	
PSCM		U3003: 68 : 28	
HCM		B1439: 87 : 08	
HCM		B14DC: 87 : 08	
HCM		B1D65: 87 : 08	
OCSM		U024C: 00 : 28	

-  Camera Module
-  Left Headlamp Swiveling Motor
-  Battery Voltage
-  Right Levelling Actuator
-  Right Headlamp Driver Control System
-  Right Headlamp Swiveling Motor
-  Lost Communication with Seat Control Module 'H'

**Time :** 11:55 AM

Odometer :  
36227 mi








★ DSM		U0422: 00 : 08	
HCM		B1D64: 87 : 08	
HCM		B1439: 87 : 08	
HCM		B14DC: 87 : 08	
HCM		B1D65: 87 : 08	
IPMA		B115E: 31 : 28	SSM / SSM
OCSM		U024C: 00 : 28	
PSCM		U3003: 68 : 28	

-  Invalid Data Received From Body Control Module
-  Left Headlamp Swiveling Motor
-  Right Levelling Actuator
-  Right Headlamp Driver Control System
-  Right Headlamp Swiveling Motor
-  Camera Module
-  Lost Communication with Seat Control Module 'H'
-  Battery Voltage

**Time :** 08:59 AM

Odometer :  
36210 mi

★ PSCM		U3003: 68 : 28	
HCM		B1D64: 87 : 08	
HCM		B1439: 87 : 08	
HCM		B14DC: 87 : 08	
HCM		B1D65: 87 : 08	
IPMA		B115E: 31 : 28	SSM / SSM
OCSM		U024C: 00 : 28	

-  Battery Voltage
-  Left Headlamp Swiveling Motor
-  Right Levelling Actuator
-  Right Headlamp Driver Control System
-  Right Headlamp Swiveling Motor
-  Camera Module
-  Lost Communication with Seat Control Module 'H'


Time : 07:16 AM

Odometer :

36194 mi

★	DSM		U0422: 00 : 08
★	HCM		B1D65: 87 : 08
★	HCM		B14DC: 87 : 08
★	HCM		B1439: 87 : 08
★	HCM		B1D64: 87 : 08
★	IPMA		B115E: 31 : 28
★	OCSM		U024C: 00 : 28
★	PSCM		U3003: 68 : 2C

[SSM](#) / [SSM](#)

-  Invalid Data Received From Body Control Module
-  Right Headlamp Swiveling Motor
-  Right Headlamp Driver Control System
-  Right Levelling Actuator
-  Left Headlamp Swiveling Motor
-  Camera Module
-  Lost Communication with Seat Control Module 'H'
-  Battery Voltage