

Vin: 1FTFW1E13MFB77676

Connected Vehicle Status

Units ⚙️

Last Vehicle Status Update: March 01, 2024 09:21 AM
*Note: Do not use as a pressure gauge

Refresh

Odometer



39250 Miles

Fuel Level



Fuel Level: 13%
Fuel Range: 87 Miles to empty

Tire Pressure (PSI)*



Recommended Tire Pressure(cold)
Front : 35 | Rear : 35

Oil Life Remaining



0%

Diesel Exhaust Fluid



Exhaust Fluid Level: 92%
Distance To Empty: 6000 Miles

60-Day VHA/DTC History

Last Vehicle Health Update: March 01, 2024 09:13 AM

January 2024

Sun	Mon	Tue	Wed	Thu
	1	2	3	4
7	8	9	10	11
14	15	16	17	18
21	22	23	24	25
28	29	30	31	

February 2024

Sun	Mon	Tue	Wed	Thu
				1
4	5	6	7	8
11	12	13	14	15
18	19	20	21	22
25	26	27	28	29

March 2024

Sun	Mon	Tue	Wed	Thu
3	4	5	6	7
10	11	12	13	14
17	18	19	20	21
24	25	26	27	28
31				

Vehicle Health Alerts (VHA) and Diagnostic Trouble Codes (DTC)

Date | Time | Odometer

Event Description

★

Module

|

DTC

: FT : SB

TSB/GSB/SSM

Send to Search

Description

March 01, 2024

Select All

Time : 09:13 AM	★ PCM	P0E4E: 00 : 28	☐ ⚠ Engine Failed to Crank
Odometer : 39250 mi	★ PSCM	U3003: 68 : 28	☐ ⚠ Battery Voltage

February 28, 2024

Time : 10:32 AM	🛢️ New Alert - Oil
Odometer : 39250 mi	Change Required

February 22, 2024

Time : 03:57 PM	⚠ No DTCs Present
Odometer : 39250 mi	

February 13, 2024

Select All

Time : 03:39 PM	★ HCM	B1D64: 87 : 0B	☐ ⚠ Left Headlamp Swiveling Motor
Odometer : 39027 mi	★ HCM	B14DB: 87 : 0B	☐ ⚠ Left Headlamp Driver Control System
	★ HCM	B1437: 87 : 0B	☐ ⚠ Left Levelling Actuator
	★ IPMA	U0565: 82 : 2C	☐ ⚠ Invalid Data Received From Camera Module-Rear
	HCM	B1439: 87 : 08	☐ ⚠ Right Levelling Actuator
	HCM	B1D65: 87 : 08	☐ ⚠ Right Headlamp Swiveling Motor
	OCSM	U024C: 00 : 28	☐ ⚠ Lost Communication with Seat Control Module 'H'

February 12, 2024

☐ Select All

Time : 09:23 PM  New Alert - Change
Odometer : Engine Oil Soon
38917 mi

Time : 06:42 AM
Odometer :
38799 mi

★	HCM		B14DB: 87 : 08
★	HCM		B1D65: 87 : 08
★	HCM		B1437: 87 : 08
★	HCM		B14DC: 87 : 08
★	HCM		B1439: 87 : 08
★	HCM		B1D64: 87 : 08
	OCSM		U024C: 00 : 28

☐		Left Headlamp Driver Control System
☐		Right Headlamp Swiveling Motor
☐		Left Levelling Actuator
☐		Right Headlamp Driver Control System
☐		Right Levelling Actuator
☐		Left Headlamp Swiveling Motor
☐		Lost Communication with Seat Control Module 'H'

February 11, 2024

☐ Select All

Time : 11:37 AM  Clear Alert - Washer
Odometer : Fluid Low
38746 mi

HCM		B14DC: 87 : 0A
HCM		B1439: 87 : 0A
HCM		B1D65: 87 : 0A
OCSM		U024C: 00 : 28
HCM		B1D64: 87 : 0A

☐		Right Headlamp Driver Control System
☐		Right Levelling Actuator
☐		Right Headlamp Swiveling Motor
☐		Lost Communication with Seat Control Module 'H'
☐		Left Headlamp Swiveling Motor

Time : 10:14 AM  New Alert - Washer [Show](#)
Odometer : Fluid Low [Details](#)
38738 mi

HCM		B14DC: 87 : 0A
HCM		B1439: 87 : 0A
HCM		B1D65: 87 : 0A
OCSM		U024C: 00 : 28
HCM		B1D64: 87 : 0A

☐		Right Headlamp Driver Control System
☐		Right Levelling Actuator
☐		Right Headlamp Swiveling Motor
☐		Lost Communication with Seat Control Module 'H'
☐		Left Headlamp Swiveling Motor

February 05, 2024

☐ Select All

Time : 04:36 PM
Odometer :
38378 mi

★	HCM		B1D64: 87 : 0A
★	HCM		B1D65: 87 : 0A
★	HCM		B1439: 87 : 0A
★	HCM		B14DC: 87 : 0A
	OCSM		U024C: 00 : 28

☐		Left Headlamp Swiveling Motor
☐		Right Headlamp Swiveling Motor
☐		Right Levelling Actuator
☐		Right Headlamp Driver Control System
☐		Lost Communication with Seat Control Module 'H'

February 04, 2024

☐ Select All

Time : 08:09 AM
Odometer :
38328 mi

★	HCM		B1D65: 87 : 08
★	HCM		B1439: 87 : 08
★	HCM		B1D64: 87 : 08
★	OCSM		U024C: 00 : 28

- ☐  Right Headlamp Swiveling Motor
- ☐  Right Levelling Actuator
- ☐  Left Headlamp Swiveling Motor
- ☐  Lost Communication with Seat Control Module 'H'

February 03, 2024

Time : 08:37 AM
Odometer :
38309 mi

 No DTCs Present

February 02, 2024

☐ Select All

Time : 05:21 PM
 OTA On-Vehicle
Activity-Update
Activation is
finished

Time : 05:16 PM
 OTA On-Vehicle
Activity-Vehicle
Activation Start

Time : 05:03 PM
Odometer :
38272 mi

★	OCSM		U024C: 00 : 28
	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	HCM		B1437: 87 : 08
	HCM		B1D65: 87 : 08
	HCM		B14DB: 87 : 08

- ☐  Lost Communication with Seat Control Module 'H'
- ☐  Left Headlamp Swiveling Motor
- ☐  Right Levelling Actuator
- ☐  Left Levelling Actuator
- ☐  Right Headlamp Swiveling Motor
- ☐  Left Headlamp Driver Control System

January 29, 2024

Time : 07:37 AM
Odometer :
38000 mi

 New Alert - Time to
Plan

January 26, 2024

☐ Select All

Time : 06:24 AM
Odometer :
37832 mi

★	HCM		B14DB: 87 : 08
★	HCM		B1437: 87 : 08
★	HCM		B15A7: 87 : 08
★	OCSM		U024C: 00 : 2A
	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	HCM		B1D65: 87 : 08

- ☐ ⚠ Left Headlamp Driver Control System
- ☐ ⚠ Left Levelling Actuator
- ☐ ⚠ Left Matrix Controller Actuator
- ☐ ⚠ Lost Communication with Seat Control Module 'H'
- ☐ ⚠ Left Headlamp Swiveling Motor
- ☐ ⚠ Right Levelling Actuator
- ☐ ⚠ Right Headlamp Swiveling Motor

January 23, 2024

☐ Select All

Time : 06:56 AM
Odometer :
37634 mi

★	HCM		B1D65: 87 : 08
★	HCM		B1439: 87 : 08
★	HCM		B1D64: 87 : 08
	OCSM		U024C: 00 : 28

- ☐ ⚠ Right Headlamp Swiveling Motor
- ☐ ⚠ Right Levelling Actuator
- ☐ ⚠ Left Headlamp Swiveling Motor
- ☐ ⚠ Lost Communication with Seat Control Module 'H'

January 22, 2024

☐ Select All

Time : 07:12 PM
Odometer :
37623 mi

	OCSM		U024C: 00 : 28
--	------	--	----------------

- ☐ ⚠ Lost Communication with Seat Control Module 'H'

Time : 06:59 AM
Odometer :
37556 mi

★	HCM		B14DB: 87 : 08
★	HCM		B1D65: 87 : 08
★	HCM		B1437: 87 : 08
★	HCM		B1439: 87 : 08
★	HCM		B1D64: 87 : 08
★	OCSM		U024C: 00 : 28

- ☐ ⚠ Left Headlamp Driver Control System
- ☐ ⚠ Right Headlamp Swiveling Motor
- ☐ ⚠ Left Levelling Actuator
- ☐ ⚠ Right Levelling Actuator
- ☐ ⚠ Left Headlamp Swiveling Motor
- ☐ ⚠ Lost Communication with Seat Control Module 'H'

January 21, 2024

☐ Select All

Time : 08:31 PM

Odometer : 37556 mi

★ PSCM

HCM

HCM

HCM

|

B1437 : 87 : 0B

B14DB : 87 : 0B

B1D64 : 87 : 0B

☐ ⚠ Lost Communication With Image Processing Module A

☐ ⚠ Left Levelling Actuator

☐ ⚠ Left Headlamp Driver Control System

☐ ⚠ Left Headlamp Swiveling Motor

Time : 08:10 PM

Odometer : 37556 mi

HCM

HCM

HCM

|

B1437 : 87 : 0B

B14DB : 87 : 0B

B1D64 : 87 : 0B

☐ ⚠ Left Levelling Actuator

☐ ⚠ Left Headlamp Driver Control System

☐ ⚠ Left Headlamp Swiveling Motor

Time : 07:43 PM

Odometer : 37556 mi

★ HCM

★ HCM

★ HCM

★ SCCM

|

B1D64 : 87 : 0B

B14DB : 87 : 0B

B1437 : 87 : 0B

U2101 : 00 : 2A

SSM

☐ ⚠ Left Headlamp Swiveling Motor

☐ ⚠ Left Headlamp Driver Control System

☐ ⚠ Left Levelling Actuator

☐ ⚠ Control Module Configuration Incompatible

Time : 11:24 AM

Odometer : 37545 mi

★ HCM

★ HCM

★ HCM

|

B14DB : 87 : 0B

B1437 : 87 : 0B

B1D64 : 87 : 0B

☐ ⚠ Left Headlamp Driver Control System

☐ ⚠ Left Levelling Actuator

☐ ⚠ Left Headlamp Swiveling Motor

Time : 09:26 AM

Odometer : 37544 mi

★ DSM

★ HCM

★ HCM

★ HCM

OCSM

|

U0422 : 00 : 0B

B1D64 : 87 : 0B

B14DB : 87 : 0B

B1437 : 87 : 0B

U024C : 00 : 28

☐ ⚠ Invalid Data Received From Body Control Module

☐ ⚠ Left Headlamp Swiveling Motor

☐ ⚠ Left Headlamp Driver Control System

☐ ⚠ Left Levelling Actuator

☐ ⚠ Lost Communication with Seat Control Module 'H'

Time : 08:07 AM

Odometer : 37524 mi

★ OCSM

|

U024C : 00 : 28

☐ ⚠ Lost Communication with Seat Control Module 'H'

January 20, 2024

Time : 03:52 PM

Odometer : 37518 mi

⚠ No DTCs Present

January 19, 2024

☐ Select All

Time : 05:09 PM
Odometer :
37482 mi

★	HCM		B1D64: 87 : 0A
★	HCM		B1D65: 87 : 0A
★	HCM		B1439: 87 : 0A
	OCSM		U024C: 00 : 28

- ☐  Left Headlamp Swiveling Motor
- ☐  Right Headlamp Swiveling Motor
- ☐  Right Levelling Actuator
- ☐  Lost Communication with Seat Control Module 'H'

Time : 07:06 AM
Odometer :
37453 mi

★	DSM		U0422: 00 : 08
	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	HCM		B1D65: 87 : 08
	OCSM		U024C: 00 : 28

- ☐  Invalid Data Received From Body Control Module
- ☐  Left Headlamp Swiveling Motor
- ☐  Right Levelling Actuator
- ☐  Right Headlamp Swiveling Motor
- ☐  Lost Communication with Seat Control Module 'H'

January 18, 2024

☐ Select All

Time : 04:14 PM
Odometer :
37415 mi

	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	HCM		B1D65: 87 : 08
	OCSM		U024C: 00 : 28

- ☐  Left Headlamp Swiveling Motor
- ☐  Right Levelling Actuator
- ☐  Right Headlamp Swiveling Motor
- ☐  Lost Communication with Seat Control Module 'H'

Time : 07:10 AM
Odometer :
37387 mi

	OCSM		U024C: 00 : 28
	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	DSM		U0422: 00 : 08
	HCM		B1D65: 87 : 08

- ☐  Lost Communication with Seat Control Module 'H'
- ☐  Left Headlamp Swiveling Motor
- ☐  Right Levelling Actuator
- ☐  Invalid Data Received From Body Control Module
- ☐  Right Headlamp Swiveling Motor

January 15, 2024

☐ Select All

Time : 06:53 AM
Odometer :
37266 mi

★	DSM		U0422: 00 : 08
★	PSCM		U3003: 68 : 2E
	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	HCM		B14DC: 87 : 08
	HCM		B1437: 87 : 08
	HCM		B1D65: 87 : 08
	HCM		B14DB: 87 : 08
	OCSM		U024C: 00 : 28

- ☐  Invalid Data Received From Body Control Module
- ☐  Battery Voltage
- ☐  Left Headlamp Swiveling Motor
- ☐  Right Levelling Actuator
- ☐  Right Headlamp Driver Control System
- ☐  Left Levelling Actuator
- ☐  Right Headlamp Swiveling Motor
- ☐  Left Headlamp Driver Control System
- ☐  Lost Communication with Seat Control Module 'H'

January 14, 2024

☐ Select All

Time : 12:26 PM
Odometer :
37249 mi

★	OCSM		U024C: 00 : 28
★	PSCM		U3003: 68 : 28
	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	HCM		B14DC: 87 : 08
	HCM		B1437: 87 : 08
	HCM		B1D65: 87 : 08
	HCM		B14DB: 87 : 08

- ☐  Lost Communication with Seat Control Module 'H'
- ☐  Battery Voltage
- ☐  Left Headlamp Swiveling Motor
- ☐  Right Levelling Actuator
- ☐  Right Headlamp Driver Control System
- ☐  Left Levelling Actuator
- ☐  Right Headlamp Swiveling Motor
- ☐  Left Headlamp Driver Control System

Time : 08:32 AM
Odometer :
37220 mi

★	DSM		U0422: 00 : 08
★	HCM		B1D65: 87 : 08
★	HCM		B1439: 87 : 08
★	PSCM		U3003: 68 : 2E
	HCM		B1D64: 87 : 08
	HCM		B14DC: 87 : 08
	HCM		B1437: 87 : 08
	HCM		B14DB: 87 : 08
	OCSM		U024C: 00 : 2A

- ☐  Invalid Data Received From Body Control Module
- ☐  Right Headlamp Swiveling Motor
- ☐  Right Levelling Actuator
- ☐  Battery Voltage
- ☐  Left Headlamp Swiveling Motor
- ☐  Right Headlamp Driver Control System
- ☐  Left Levelling Actuator
- ☐  Left Headlamp Driver Control System
- ☐  Lost Communication with Seat Control Module 'H'

January 12, 2024

☐ Select All

Time : 04:58 PM
Odometer :
37155 mi

★	HCM		B14DB: 87 : 08
★	HCM		B1D65: 87 : 0A
★	HCM		B1437: 87 : 08
★	HCM		B1439: 87 : 0A
★	HCM		B1D64: 87 : 08
★	OCSM		U024C: 00 : 2A
★	PSCM		U3003: 68 : 28
	HCM		B14DC: 87 : 08

- ☐ ⚠ Left Headlamp Driver Control System
- ☐ ⚠ Right Headlamp Swiveling Motor
- ☐ ⚠ Left Levelling Actuator
- ☐ ⚠ Right Levelling Actuator
- ☐ ⚠ Left Headlamp Swiveling Motor
- ☐ ⚠ Lost Communication with Seat Control Module 'H'
- ☐ ⚠ Battery Voltage
- ☐ ⚠ Right Headlamp Driver Control System

Time : 08:08 AM
Odometer :
37143 mi

★	HCM		B1D64: 87 : 0B
★	HCM		B14DB: 87 : 0B
★	HCM		B1437: 87 : 0B
★	PSCM		U3003: 68 : 2C
	HCM		B1439: 87 : 08
	HCM		B14DC: 87 : 08
	HCM		B1D65: 87 : 08

- ☐ ⚠ Left Headlamp Swiveling Motor
- ☐ ⚠ Left Headlamp Driver Control System
- ☐ ⚠ Left Levelling Actuator
- ☐ ⚠ Battery Voltage
- ☐ ⚠ Right Levelling Actuator
- ☐ ⚠ Right Headlamp Driver Control System
- ☐ ⚠ Right Headlamp Swiveling Motor

January 11, 2024

☐ Select All

Time : 03:48 PM
Odometer :
37143 mi

★	HCM		B14DC: 87 : 08
	HCM		B1D64: 87 : 08
	HCM		B1439: 87 : 08
	HCM		B1D65: 87 : 08

- ☐ ⚠ Right Headlamp Driver Control System
- ☐ ⚠ Left Headlamp Swiveling Motor
- ☐ ⚠ Right Levelling Actuator
- ☐ ⚠ Right Headlamp Swiveling Motor

January 09, 2024

☐ Select All

Time : 10:23 AM
Odometer :
37141 mi



Clear Alert - Washer
Fluid Low

★	HCM		B1D65: 87 : 08
★	HCM		B1439: 87 : 08
★	HCM		B1D64: 87 : 08

- ☐ ⚠ Right Headlamp Swiveling Motor
- ☐ ⚠ Right Levelling Actuator
- ☐ ⚠ Left Headlamp Swiveling Motor

January 08, 2024

Time : 02:53 PM

Odometer :

37139 mi



New Alert - Washer
Fluid Low

[Show](#)

[Details](#)



No DTCs Present

Time : 10:42 AM

Odometer : 37139 mi



Clear Alert - Washer Fluid Low

★ PSCM

|

U3003: 68 : 2E

DSM

|

U0422: 00 : 08

HCM

|

B1D64: 87 : 08

HCM

|

B1439: 87 : 08

HCM

|

B1D65: 87 : 08

OCSM

|

U024C: 00 : 28

PSCM

|

U0415: 00 : 28

TSB

☐  Battery Voltage

☐  Invalid Data Received From Body Control Module

☐  Left Headlamp Swiveling Motor

☐  Right Levelling Actuator

☐  Right Headlamp Swiveling Motor

☐  Lost Communication with Seat Control Module 'H'

☐  Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 09:09 AM

Odometer : 37128 mi



New Alert - Washer Fluid Low [Show Details](#)

HCM

|

B1D64: 87 : 08

HCM

|

B1439: 87 : 08

DSM

|

U0422: 00 : 08

HCM

|

B1D65: 87 : 08

OCSM

|

U024C: 00 : 28

PSCM

|

U0415: 00 : 28

TSB

☐  Left Headlamp Swiveling Motor

☐  Right Levelling Actuator

☐  Invalid Data Received From Body Control Module

☐  Right Headlamp Swiveling Motor

☐  Lost Communication with Seat Control Module 'H'

☐  Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 09:07 AM

Odometer : 37126 mi



Clear Alert - Washer Fluid Low

★ DSM

|

U0422: 00 : 08

★ HCM

|

B1D65: 87 : 08

★ HCM

|

B1439: 87 : 08

★ HCM

|

B1D64: 87 : 08

★ OCSM

|

U024C: 00 : 28

★ PSCM

|

U0415: 00 : 28

TSB

☐  Invalid Data Received From Body Control Module

☐  Right Headlamp Swiveling Motor

☐  Right Levelling Actuator

☐  Left Headlamp Swiveling Motor

☐  Lost Communication with Seat Control Module 'H'

☐  Invalid Data Received from Anti-Lock Brake System (ABS) Control Module 'A'

Time : 07:02 AM

Odometer : 37100 mi



New Alert - Washer Fluid Low [Show Details](#)

Time : 07:00 AM

Odometer : 37098 mi



Clear Alert - Washer Fluid Low

January 01, 2024

Time : 03:47 PM

Odometer : 37028 mi



New Alert - Washer Fluid Low

[Show Details](#)

Time : 03:46 PM

Odometer : 37026 mi



Clear Alert - Washer Fluid Low