

Last Vehicle Status Update: 08-August-2024 10:39 AM
*Note: Do not use as a pressure gauge

Refresh

Odometer



64154 Miles

Fuel Level



Fuel Level: 54%
Fuel Range: 419 Miles to empty

Tire Pressure (PSI)*



Recommended Tire Pressure(cold)
Front : 35 | Rear : 35

Oil Life Remaining



59%

Action required:None
Estimated distance remaining:
5300 Miles
Estimated date for oil change:Oct 2024

12V Battery



Battery State of Charge : 81%
Battery Voltage : 14.2V

60-Day VHA/DTC History

Last Vehicle Health Update:08-August-2024 09:26 PM

June 2024

Sun	Mon	Tue	Wed	Thu
2	3	4	5	6
9	10	11	12	13
16	17	18	19	20
23	24	25	26	27
30				

July 2024

Sun	Mon	Tue	Wed	Thu
	1	2	3	4
7	8	9	10	11
14	15	16	17	18
21	22	23	24	25
28	29	30	31	

August 2024

Sun	Mon	Tue	Wed	Thu
				1
4	5	6	7	8
11	12	13	14	15
18	19	20	21	22
25	26	27	28	29

Vehicle Health Alerts (VHA) and Diagnostic Trouble Codes (DTC)

Date Time Odometer	Event Description	Module	DTC	FT : SB	TSB/GSB/SSM	Send to Search	Description
08-August-2024							
Time : 09:26 AM Odometer : 64072 mi		IPMA	B1578	78	2F	☐	Digital Park Assist Camera Vision System
		OCSM	U024C	00	28	☐	Lost Communication with Seat Control Module 'H'
		TCU	U0146	09	08	☐	Lost Communication With Serial Data Gateway Module 'A'

Time : 07:32 PM Odometer : 63824 mi	IPMA B1578 : 78 : 2F OCSM U024C : 00 : 28 TCU U0146 : 09 : 08	☐  Digital Park Assist Camera Vision System ☐  Lost Communication with Seat Control Module 'H' ☐  Lost Communication With Serial Data Gateway Module 'A'
Time : 06:22 PM Odometer : 63822 mi	IPMA U0565 : 82 : 28 IPMA B1578 : 78 : 2F TCU U0146 : 09 : 08 OCSM U024C : 00 : 28	☐  Invalid Data Received From Camera Module - Rear ☐  Digital Park Assist Camera Vision System ☐  Lost Communication With Serial Data Gateway Module 'A' ☐  Lost Communication with Seat Control Module 'H'

Time : 08:31 PM Odometer : 63816 mi	IPMA		U0565: 82 : 28	☐  Invalid Data Received From Camera Module - Rear
	IPMA		B1578: 78 : 2F	☐  Digital Park Assist Camera Vision System
	TCU		U0146: 09 : 08	☐  Lost Communication With Serial Data Gateway Module 'A'
	IPMA		B152E: 08 : 28	☐  Rear Camera 2
	OCSM		U024C: 00 : 28	☐  Lost Communication with Seat Control Module 'H'

Time : 11:57 AM Odometer : 63796 mi	★ TCU		U0146: 09 : 08	☐  Lost Communication With Serial Data Gateway Module 'A'
	IPMA		U0565: 82 : 28	☐  Invalid Data Received From Camera Module - Rear
	IPMA		B1578: 78 : 2F	☐  Digital Park Assist Camera Vision System
	IPMA		B152E: 08 : 28	☐  Rear Camera 2
	IPMA		B1385: 68 : 28	☐  Lane Keeping Aid System
	OCSM		U024C: 00 : 28	☐  Lost Communication with Seat Control Module 'H'

Time : 09:46 AM Odometer : 63794 mi	IPMA		U0565: 82 : 28	☐  Invalid Data Received From Camera Module - Rear
	IPMA		B1578: 78 : 2F	☐  Digital Park Assist Camera Vision System
	GWM		U2402: 00 : 0B	☐  Ethernet Failure With Telematic Control Unit Module (TCU)
	TCU		U0146: 09 : 0B	☐  Lost Communication With Serial Data Gateway Module 'A'
	IPMA		B152E: 08 : 28	☐  Rear Camera 2
	IPMA		B1385: 68 : 28	☐  Lane Keeping Aid System
	OCSM		U024C: 00 : 28	☐  Lost Communication with Seat Control Module 'H'
	IPMA		U0565: 82 : 28	☐  Invalid Data Received From Camera Module - Rear
	IPMA		B1578: 78 : 2F	☐  Digital Park Assist Camera Vision System
	GWM		U2402: 00 : 0B	☐  Ethernet Failure With Telematic Control Unit Module (TCU)
	TCU		U0146: 09 : 0B	☐  Lost Communication With Serial Data Gateway Module 'A'
	IPMA		B152E: 08 : 28	☐  Rear Camera 2
	IPMA		B1385: 68 : 28	☐  Lane Keeping Aid System
	OCSM		U024C: 00 : 28	☐  Lost Communication with Seat Control Module 'H'

Time : 09:29 AM Odometer : 63791 mi	★ GWM		U2402: 00 : 0B	☐  Ethernet Failure With Telematic Control Unit Module (TCU)
--	-------	--	-----------------------	--

	★	GWM		U2402: 00 : 0B	☐	⚠	Ethernet Failure With Telematic Control Unit Module (TCU)
	★	OCSM		U024C: 00 : 28	☐	⚠	Lost Communication with Seat Control Module 'H'
	★	OCSM		U024C: 00 : 28	☐	⚠	Lost Communication with Seat Control Module 'H'
	★	TCU		U0146: 09 : 0B	☐	⚠	Lost Communication With Serial Data Gateway Module 'A'
	★	TCU		U0146: 09 : 0B	☐	⚠	Lost Communication With Serial Data Gateway Module 'A'
		IPMA		U0565: 82 : 28	☐	⚠	Invalid Data Received From Camera Module - Rear
		IPMA		B1578: 78 : 2F	☐	⚠	Digital Park Assist Camera Vision System
		IPMA		B152E: 08 : 28	☐	⚠	Rear Camera 2
		IPMA		B1385: 68 : 28	☐	⚠	Lane Keeping Aid System
		IPMA		U0565: 82 : 28	☐	⚠	Invalid Data Received From Camera Module - Rear
		IPMA		B1578: 78 : 2F	☐	⚠	Digital Park Assist Camera Vision System
		IPMA		B152E: 08 : 28	☐	⚠	Rear Camera 2
		IPMA		B1385: 68 : 28	☐	⚠	Lane Keeping Aid System

28-July-2024

Time : 12:46 PM Odometer : 63719 mi	★	IPMA		B152E: 08 : 28	☐	⚠	Rear Camera 2
	★	IPMA		U0565: 82 : 28	☐	⚠	Invalid Data Received From Camera Module - Rear
	★	OCSM		U024C: 00 : 2A	☐	⚠	Lost Communication with Seat Control Module 'H'
		IPMA		B1578: 78 : 2F	☐	⚠	Digital Park Assist Camera Vision System
		IPMA		B1385: 68 : 28	☐	⚠	Lane Keeping Aid System

27-July-2024

Time : 11:34 AM Odometer : 63700 mi		Clear Alert - Fuel Level Low			☐	Select All	
		IPMA		B1578: 78 : 2F	☐	⚠	Digital Park Assist Camera Vision System
		IPMA		U0565: 82 : 2E	☐	⚠	Invalid Data Received From Camera Module - Rear
		IPMA		B152E: 08 : 2C	☐	⚠	Rear Camera 2
		IPMA		B1385: 68 : 28	☐	⚠	Lane Keeping Aid System

Time : 07:21 PM Odometer : 63665 mi  New Alert - Fuel Level Low Show Details	IPMA B1578 : 78 : 2F IPMA U0565 : 82 : 2E IPMA B152E : 08 : 2C IPMA B1385 : 68 : 28	☐  Digital Park Assist Camera Vision System ☐  Invalid Data Received From Camera Module - Rear ☐  Rear Camera 2 ☐  Lane Keeping Aid System
Time : 10:33 AM Odometer : 63429 mi	★ IPMA U0565 : 82 : 2E IPMA B1578 : 78 : 2F IPMA B152E : 08 : 2C IPMA B1385 : 68 : 28	☐  Invalid Data Received From Camera Module - Rear ☐  Digital Park Assist Camera Vision System ☐  Rear Camera 2 ☐  Lane Keeping Aid System
Time : 10:19 AM Odometer : 63422 mi	★ IPMA B1385 : 68 : 28 ★ IPMA B152E : 08 : 2C IPMA B1578 : 78 : 2F	☐  Lane Keeping Aid System ☐  Rear Camera 2 ☐  Digital Park Assist Camera Vision System

Time : 07:59 PM Odometer : 63414 mi		★ IPMA IPMA		B1385 : 68 : 2C B1578 : 78 : 2F		☐ ⚠ Lane Keeping Aid System ☐ ⚠ Digital Park Assist Camera Vision System	
Time : 04:26 PM Odometer : 63341 mi  Clear Alert - Powertrain System Fault  Clear Alert - Powertrain System Fault		IPMA IPMA PCM IPMA IPMA IPMA PDM OCSM		B1578 : 78 : 2F B1578 : 89 : 2E P084B : 00 : AF B1385 : 68 : 2E B1578 : 78 : 2F B152E : 08 : 28 B108F : 23 : 48 U024C : 00 : 28		☐ ⚠ Digital Park Assist Camera Vision System ☐ ⚠ Digital Park Assist Camera Vision System ☐ ⚠ Transmission Fluid Pressure Sensor/Switch 'H' Circuit Range/Performance ☐ ⚠ Lane Keeping Aid System ☐ ⚠ Digital Park Assist Camera Vision System ☐ ⚠ Rear Camera 2 ☐ ⚠ Cabin Lock/Unlock Switch ☐ ⚠ Lost Communication with Seat Control Module 'H'	
Time : 04:00 PM Odometer : 63332 mi  New Alert - Powertrain System Fault  New Alert - Powertrain System Fault Show Details Show Details		★ IPMA ★ IPMA ★ IPMA ★ PCM IPMA IPMA IPMA IPMA OCSM OCSM PCM PDM PDM		B152E : 08 : 28 B1385 : 68 : 2E B1578 : 89 : 2E P084B : 00 : AF B1578 : 89 : 2E B1385 : 68 : 2E B1578 : 78 : 2F B152E : 08 : 28 B1578 : 78 : 2F U024C : 00 : 28 U024C : 00 : 28 P084B : 00 : AF B108F : 23 : 48 B108F : 23 : 48		☐ ⚠ Rear Camera 2 ☐ ⚠ Lane Keeping Aid System ☐ ⚠ Digital Park Assist Camera Vision System ☐ ⚠ Transmission Fluid Pressure Sensor/Switch 'H' Circuit Range/Performance ☐ ⚠ Digital Park Assist Camera Vision System ☐ ⚠ Lane Keeping Aid System ☐ ⚠ Digital Park Assist Camera Vision System ☐ ⚠ Rear Camera 2 ☐ ⚠ Digital Park Assist Camera Vision System ☐ ⚠ Lost Communication with Seat Control Module 'H' ☐ ⚠ Lost Communication with Seat Control Module 'H' ☐ ⚠ Transmission Fluid Pressure Sensor/Switch 'H' Circuit Range/Performance ☐ ⚠ Cabin Lock/Unlock Switch ☐ ⚠ Cabin Lock/Unlock Switch	

24-July-2024

☐ Select All

Time : 12:58 PM
Odometer :
63199 mi

★	IPMA		B152E : 08 : 2C
	IPMA		B1578 : 78 : 2F
	OCSM		U024C : 00 : 28
	PDM		B108F : 23 : 48

- ☐ ⚠ Rear Camera 2
- ☐ ⚠ Digital Park Assist Camera Vision System
- ☐ ⚠ Lost Communication with Seat Control Module 'H'
- ☐ ⚠ Cabin Lock/Unlock Switch

21-July-2024

☐ Select All

Time : 01:55 PM
Odometer :
63120 mi

 Clear Alert - Fuel
Level Low

	CMR		B15E1 : 97 : 0E	SSM
	IPMA		B1578 : 78 : 2F	
	IPMA		B152E : 08 : 28	
	PDM		B108F : 23 : 48	
	OCSM		U024C : 00 : 28	

- ☐ ⚠ Driver Side LED
- ☐ ⚠ Digital Park Assist Camera Vision System
- ☐ ⚠ Rear Camera 2
- ☐ ⚠ Cabin Lock/Unlock Switch
- ☐ ⚠ Lost Communication with Seat Control Module 'H'

20-July-2024

☐ Select All

Time : 02:17 PM
Odometer :
63105 mi

 New Alert - Fuel
Level Low [Show Details](#)

	CMR		B15E1 : 97 : 0E	SSM
	IPMA		B1578 : 78 : 2F	
	IPMA		B152E : 08 : 28	
	PDM		B108F : 23 : 48	
	OCSM		U024C : 00 : 28	

- ☐ ⚠ Driver Side LED
- ☐ ⚠ Digital Park Assist Camera Vision System
- ☐ ⚠ Rear Camera 2
- ☐ ⚠ Cabin Lock/Unlock Switch
- ☐ ⚠ Lost Communication with Seat Control Module 'H'

14-July-2024

☐ Select All

Time : 05:23 PM
Odometer :
62611 mi

★	CMR		B15E1 : 97 : 0E	SSM
	IPMA		B1578 : 78 : 2F	
	IPMA		B152E : 08 : 28	
	OCSM		U024C : 00 : 28	
	PDM		B108F : 23 : 48	

- ☐ ⚠ Driver Side LED
- ☐ ⚠ Digital Park Assist Camera Vision System
- ☐ ⚠ Rear Camera 2
- ☐ ⚠ Lost Communication with Seat Control Module 'H'
- ☐ ⚠ Cabin Lock/Unlock Switch

10-July-2024

☐ Select All

Time : 08:49 AM
Odometer :
62494 mi

★	IPMA		B152E: 08 : 28
	IPMA		B1578: 78 : 2F
	OCSM		U024C: 00 : 28
	PDM		B108F: 23 : 48

- ☐  Rear Camera 2
- ☐  Digital Park Assist Camera Vision System
- ☐  Lost Communication with Seat Control Module 'H'
- ☐  Cabin Lock/Unlock Switch

08-July-2024

☐ Select All

Time : 09:27 AM
Odometer :
62436 mi

★	IPMA		B152E: 08 : 2C
	IPMA		B1578: 78 : 2F
	OCSM		U024C: 00 : 28
	PDM		B108F: 23 : 48
	TCU		U0146: 09 : 08

- ☐  Rear Camera 2
- ☐  Digital Park Assist Camera Vision System
- ☐  Lost Communication with Seat Control Module 'H'
- ☐  Cabin Lock/Unlock Switch
- ☐  Lost Communication With Serial Data Gateway Module 'A'

05-July-2024

☐ Select All

Time : 09:49 PM
Odometer :
61702 mi

★	CMR		B15E1: 97 : 08	SSM
★	OCSM		U024C: 00 : 28	
	IPMA		B1578: 78 : 2F	
	PDM		B108F: 23 : 48	
	TCU		U0146: 09 : 08	

- ☐  Driver Side LED
- ☐  Lost Communication with Seat Control Module 'H'
- ☐  Digital Park Assist Camera Vision System
- ☐  Cabin Lock/Unlock Switch
- ☐  Lost Communication With Serial Data Gateway Module 'A'

Time : 11:21 PM

Odometer : 61078 mi



Clear Alert - Fuel Level Low

CMR | B15E1 : 97 : 0C

IPMA | B1578 : 78 : 2F

TCU | U0146 : 09 : 08

PDM | B108F : 23 : 48

IPMA | B1385 : 68 : 28

OCSM | U024C : 00 : 2A

SSM

☐  Driver Side LED

☐  Digital Park Assist Camera Vision System

☐  Lost Communication With Serial Data Gateway Module 'A'

☐  Cabin Lock/Unlock Switch

☐  Lane Keeping Aid System

☐  Lost Communication with Seat Control Module 'H'

Time : 10:52 PM

Odometer : 61062 mi



New Alert - Fuel Level Low

[Show Details](#)

CMR | B15E1 : 97 : 0C

IPMA | B1578 : 78 : 2F

TCU | U0146 : 09 : 08

PDM | B108F : 23 : 48

IPMA | B1385 : 68 : 28

OCSM | U024C : 00 : 2A

SSM

☐  Driver Side LED

☐  Digital Park Assist Camera Vision System

☐  Lost Communication With Serial Data Gateway Module 'A'

☐  Cabin Lock/Unlock Switch

☐  Lane Keeping Aid System

☐  Lost Communication with Seat Control Module 'H'

Time : 09:01 PM

Odometer : 60923 mi

★ CMR | B15E1 : 97 : 0C

★ IPMA | B1385 : 68 : 28

★ OCSM | U024C : 00 : 2A

IPMA | B1578 : 78 : 2F

PDM | B108F : 23 : 48

TCU | U0146 : 09 : 08

SSM

☐  Driver Side LED

☐  Lane Keeping Aid System

☐  Lost Communication with Seat Control Module 'H'

☐  Digital Park Assist Camera Vision System

☐  Cabin Lock/Unlock Switch

☐  Lost Communication With Serial Data Gateway Module 'A'

Time : 04:25 PM

Odometer : 60817 mi

★ IPMA | B1385 : 68 : 2E

IPMA | B1578 : 78 : 2F

OCSM | U024C : 00 : 28

PDM | B108F : 23 : 48

TCU | U0146 : 09 : 08

☐  Lane Keeping Aid System

☐  Digital Park Assist Camera Vision System

☐  Lost Communication with Seat Control Module 'H'

☐  Cabin Lock/Unlock Switch

☐  Lost Communication With Serial Data Gateway Module 'A'

Time : 12:13 PM

Odometer : 60642 mi

★ TCU | U0146 : 09 : 08

IPMA | B1578 : 78 : 2F

OCSM | U024C : 00 : 28

☐  Lost Communication With Serial Data Gateway Module 'A'

☐  Digital Park Assist Camera Vision System

☐  Lost Communication with Seat Control Module 'H'

Time : 11:12 AM

Odometer :
60637 mi

PDM		B108F : 23 : 48
IPMA		B1578 : 78 : 2F
OCSM		U024C : 00 : 28
GWM		U2402 : 00 : 0B
TCU		U0146 : 09 : 0B
PDM		B108F : 23 : 48
IPMA		B1578 : 78 : 2F
OCSM		U024C : 00 : 28
GWM		U2402 : 00 : 0B
TCU		U0146 : 09 : 0B
PDM		B108F : 23 : 48
IPMA		B1578 : 78 : 2F
OCSM		U024C : 00 : 28
GWM		U2402 : 00 : 0B
TCU		U0146 : 09 : 0B

☐		Cabin Lock/Unlock Switch
☐		Digital Park Assist Camera Vision System
☐		Lost Communication with Seat Control Module 'H'
☐		Ethernet Failure With Telematic Control Unit Module (TCU)
☐		Lost Communication With Serial Data Gateway Module 'A'
☐		Cabin Lock/Unlock Switch
☐		Digital Park Assist Camera Vision System
☐		Lost Communication with Seat Control Module 'H'
☐		Ethernet Failure With Telematic Control Unit Module (TCU)
☐		Lost Communication With Serial Data Gateway Module 'A'
☐		Cabin Lock/Unlock Switch
☐		Digital Park Assist Camera Vision System
☐		Lost Communication with Seat Control Module 'H'
☐		Ethernet Failure With Telematic Control Unit Module (TCU)
☐		Lost Communication With Serial Data Gateway Module 'A'

Time : 10:47 AM

Odometer :
60634 mi

PDM		B108F : 23 : 48
IPMA		B1578 : 78 : 2F
OCSM		U024C : 00 : 28
GWM		U2402 : 00 : 0B
TCU		U0146 : 09 : 0B
PDM		B108F : 23 : 48
IPMA		B1578 : 78 : 2F
OCSM		U024C : 00 : 28
GWM		U2402 : 00 : 0B
TCU		U0146 : 09 : 0B
PDM		B108F : 23 : 48

☐		Cabin Lock/Unlock Switch
☐		Digital Park Assist Camera Vision System
☐		Lost Communication with Seat Control Module 'H'
☐		Ethernet Failure With Telematic Control Unit Module (TCU)
☐		Lost Communication With Serial Data Gateway Module 'A'
☐		Cabin Lock/Unlock Switch
☐		Digital Park Assist Camera Vision System
☐		Lost Communication with Seat Control Module 'H'
☐		Ethernet Failure With Telematic Control Unit Module (TCU)
☐		Lost Communication With Serial Data Gateway Module 'A'
☐		Cabin Lock/Unlock Switch

	IPMA		B1578 : 78 : 2F	☐  Digital Park Assist Camera Vision System
	OCSM		U024C : 00 : 28	☐  Lost Communication with Seat Control Module 'H'
	GWM		U2402 : 00 : 0B	☐  Ethernet Failure With Telematic Control Unit Module (TCU)
	TCU		U0146 : 09 : 0B	☐  Lost Communication With Serial Data Gateway Module 'A'

Time : 10:46 AM Odometer : 60634 mi	★ GWM		U2402 : 00 : 0B	☐  Ethernet Failure With Telematic Control Unit Module (TCU)
	★ GWM		U2402 : 00 : 0B	☐  Ethernet Failure With Telematic Control Unit Module (TCU)
	★ GWM		U2402 : 00 : 0B	☐  Ethernet Failure With Telematic Control Unit Module (TCU)
	★ TCU		U0146 : 09 : 0B	☐  Lost Communication With Serial Data Gateway Module 'A'
	★ TCU		U0146 : 09 : 0B	☐  Lost Communication With Serial Data Gateway Module 'A'
	★ TCU		U0146 : 09 : 0B	☐  Lost Communication With Serial Data Gateway Module 'A'
	IPMA		B1578 : 78 : 2F	☐  Digital Park Assist Camera Vision System
	IPMA		B1578 : 78 : 2F	☐  Digital Park Assist Camera Vision System
	IPMA		B1578 : 78 : 2F	☐  Digital Park Assist Camera Vision System
	OCSM		U024C : 00 : 28	☐  Lost Communication with Seat Control Module 'H'
	OCSM		U024C : 00 : 28	☐  Lost Communication with Seat Control Module 'H'
	OCSM		U024C : 00 : 28	☐  Lost Communication with Seat Control Module 'H'
	PDM		B108F : 23 : 48	☐  Cabin Lock/Unlock Switch
	PDM		B108F : 23 : 48	☐  Cabin Lock/Unlock Switch
	PDM		B108F : 23 : 48	☐  Cabin Lock/Unlock Switch

24-June-2024				☐ Select All
Time : 03:08 PM Odometer : 60555 mi	PDM		B108F : 23 : 48	☐  Cabin Lock/Unlock Switch
	IPMA		B1578 : 78 : 2F	☐  Digital Park Assist Camera Vision System
	OCSM		U024C : 00 : 28	☐  Lost Communication with Seat Control Module 'H'

23-June-2024

☐ Select All

Time : 03:29 PM
Odometer :
60538 mi

 Clear Alert - Fuel
Level Low

IPMA		B1578 : 78 : 2F
IPMA		B152E : 08 : 28
PDM		B108F : 23 : 48
OCSM		U024C : 00 : 28

- ☐  Digital Park Assist Camera Vision System
- ☐  Rear Camera 2
- ☐  Cabin Lock/Unlock Switch
- ☐  Lost Communication with Seat Control Module 'H'

22-June-2024

☐ Select All

Time : 12:41 PM
Odometer :
60511 mi

 New Alert - Fuel
Level Low [Show
Details](#)

IPMA		B1578 : 78 : 2F
IPMA		B152E : 08 : 28
PDM		B108F : 23 : 48
OCSM		U024C : 00 : 28

- ☐  Digital Park Assist Camera Vision System
- ☐  Rear Camera 2
- ☐  Cabin Lock/Unlock Switch
- ☐  Lost Communication with Seat Control Module 'H'

19-June-2024

☐ Select All

Time : 01:38 PM
Odometer :
60328 mi

IPMA		B1578 : 78 : 2F
IPMA		B152E : 08 : 28
PDM		B108F : 23 : 48
OCSM		U024C : 00 : 28

- ☐  Digital Park Assist Camera Vision System
- ☐  Rear Camera 2
- ☐  Cabin Lock/Unlock Switch
- ☐  Lost Communication with Seat Control Module 'H'

13-June-2024

Time : 07:36 PM
Odometer :
59874 mi



Clear Alert - Fuel
Level Low

IPMA		B1578 : 78 : 2F
PSCM		U023A : 00 : 2C
IPMA		B152E : 08 : 28
PDM		B108F : 23 : 48
OCSM		U024C : 00 : 28

☐ Select All

- ☐ Digital Park Assist Camera Vision System
- ☐ Lost Communication With Image Processing Module 'A'
- ☐ Rear Camera 2
- ☐ Cabin Lock/Unlock Switch
- ☐ Lost Communication with Seat Control Module 'H'

Time : 09:06 AM
Odometer :
59869 mi



Existing Alert - [Show Details](#)
Fuel Level Low

★ IPMA		B152E : 08 : 28
★ IPMA		B1578 : 78 : 2F
★ OCSM		U024C : 00 : 28
★ PDM		B108F : 23 : 48
★ PSCM		U023A : 00 : 2C

- ☐ Rear Camera 2
- ☐ Digital Park Assist Camera Vision System
- ☐ Lost Communication with Seat Control Module 'H'
- ☐ Cabin Lock/Unlock Switch
- ☐ Lost Communication With Image Processing Module 'A'

12-June-2024

Time : 10:24 PM
Odometer :
59863 mi



New Alert - Fuel [Show Details](#)
Level Low