

Request	Description	Job	CSR	Status
1	INSPECT FOR CAUSE OF TRANSMISSION CONCERN // TERRIBLE SOUND ON COLD START POWER BOOST /TAKES ABOUT 30 SECONDS TO HEAR IT AFTER START UP	1	337	Original
Labour	Description	Type	Amount	
7000A	AUTOMATIC TRANSMISSION ASSEMBLY - REMOVE AND INSTALL OR REPLACE (7000) -L	W		
7000AXQ	AUTOMATIC TRANSMISSION ASSEMBLY - REMOVE AND INSTALL OR REPLACE (7000) -L EXTRA TIME FOR POST ROAD TEST. (AFTER	W		
7000AZJ	AUTOMATIC TRANSMISSION ASSEMBLY - REMOVE AND INSTALL OR REPLACE (7000) -L EXTRA TIME TO MOUNT TRANSMISSION ON A	W		
MT	MT - ACTUAL TIME, PLEASE TYPE CORRESPONDING COMMENTS OVER THIS TEXT (TOBE USED FOR WARRANTY ITEMS ONLY)	W		
Technician	4000-			
Cause	VERIFIED- FOUND NOISE SOUNDING LIKE ARRATION COMING FROM REARWARD PART OF TRANSMISSION- PERFORMED FLUID LEVEL CHECK- EXTREMELY HARD TIME GETTING VEHICLE INTO ENGINE RUNNING DIAGNOSTIC MODE- PERFORMED FLUID LEVEL CHECK- FOUND VEHICLE 2 LITRES LOW ON TRANSMISSION FLUID- WHILE PERFORMING FLUID LEVEL CHECK- FOUND THAT FLUID WAS ARRATED ON DIPSTICK- ALSO FOUND THAT DRAIN PLUG FROM HYBRID DRIVE UNIT TO BE LEAKING TRANSMISSION FLUID	Parts Total		0.00
		Labour Total		0.00
		Request Sub-total		0.00
	02/21- LET VEHICLE SIT OVER WEEKEND AND TEST DROVE- NOISE STILL PRESENT BUT NOT AS LOUD AS PREVIOUS			
	02/28- LET VEHICLE SIT AND TESTED AGAIN- DID NOT HEAR NOISE PRESENT- HOTLINE			

Correction REMOVED TRANSMISSION- SET TRANSMISSION ON HOLDING STAND-
MTIME FOR REMOVING REPLACED HYBRID DRIVE UNIT AS NO
SERVICEABLE PART FOR COMPONENT EXISTS- PERFORMED HDU
RECALIBRATION FOR NEW UNIT- PERFORMED FLUID LEVEL CHECK-
VERIFIED REPAIR- VEHICLE NO LONGER LEAKING TRANSMISSION OIL
AND VEHICLE IS QUIETE

7000A 7.7HRS
7000AXQ 0.2HRS
7000AZJ 0.3HRS
MTIME 2.7HRS HDU REMOVAL
CASUEL: 7P209

Part	Description	Shp	Bin	Type	Price	Amount
ML3Z 7A191 A	GASKET	1	SPO	W		
ML3Z 7P209 A	MODULE - HYBRID TRAN	1	SPO	W		
HL3Z 7G090 A	SEAL	1	SPO	W		
7L1Z 4B496 C	BOLT	3	SPO	W		
ML3Z 3B478 B	CLAMP - BOOT	1	SPO	W		
XT 12 QULV	MERCON ULV 1L	7	Q3B	W		
ENVIROFEE17	ENVIROMENT FEE	7	FILECAB	W		
Technician		Parts Total				

Part	Description	Shp	Bin	Type	Price	Amount
JL3Z 7570 A	SEAL - COVER	1	SPO	W		
W716375 S900	BOLT	12	D3C	W		
ML3Z 5C226 A	GASKET	2	SPO	W		
ML3Z 7222 D	COVER	1	RM1B	W		
W718926 S900	BOLT	4	SPO	W		
W714717 S439	BOLT	1	D4H	W		
W707753 S900	STUD	1	D4A	W		
W520514 S440	NUT - HEX.	1	D5H	W		
W717136 S439	BOLT	2	D3D	W		
W520113 S440	NUT	4	D5F	W		
N800594 S100	BOLT	4	D5B	W		
7T4Z 7Z302 A	SEAL	1	SPO	W		

***IF WE REMOVED YOUR WHEELS TODAY WE RECOMMEND YOU RETURN WITHIN THE NEXT 200KM FOR A