

Vin: 1FTFW1ED



Last Vehicle He

Notice! TSBs, SSMs, and GSBs are matched by DTC and vehicle model at this time. Results may include articles that do not apply for the module specified. Please check the content of the article to ensure it applies to the module.

Date | Time | Oc

Description

Report a Problem

### SSM 51822 2023 F150 FHEV- Intermittent No Start And Stop Safely Now Message Displayed With Possible DTCs U0293 And P1A43 In The Battery Energy Control Module (BECM)

Some 2023 F150 hybrid vehicles may exhibit an intermittent no start and Stop Safely Now message displayed in the instrument panel cluster and diagnostic trouble codes (DTCs) U0293 and/or P1A43 in the BECM or in connected vehicle data. A Powertrain Control Module (PCM) software concern may be triggering the no start condition. Replacement or reprogramming of the BECM or PCM is not recommended for this condition at this time. This does not affect vehicle durability and no additional diagnosis or service is required for this condition at this time. Inform customers that the vehicle will start after leaving it off temporarily. Engineering is currently working on a solution for this condition that is expected in Q4 2023. Monitor OASIS for additional information.

Close

Back To Calendar