

Tuesday, September 20, 2022 | Mileage: 0 km

All ▼ All ▼					
Sequence	Action	Start Time	End Time	Resource ID	Technician
1	PTS : VIN 1FTFW1ED4MFA05912	11:30 AM	11:30 AM		
2	pts:connectedVehicle	11:30 AM	11:30 AM		
3	PTS : FSA : 21G01	11:30 AM	11:30 AM		
4	pts:userSelectedSetting	11:32 AM	11:32 AM		
5	PTS : VIN 1FTFW1ED4MFA05912	11:42 AM	11:42 AM		
6	pts:connectedVehicle	11:42 AM	11:42 AM		
7	PTS : VIN 1FTFW1ED4MFA05912	11:48 AM	11:48 AM		
8	PTS : Connected Vehicle Home	11:48 AM	11:48 AM		
9	pts:connectedVehicle	11:48 AM	11:48 AM		
10	PTS : VIN 1FTFW1ED4MFA05912	12:54 PM	12:54 PM		
11	pts:connectedVehicle	12:54 PM	12:54 PM		
12	PTS : Connected Vehicle Home	12:56 PM	12:56 PM		
13	PTS : Connected Vehicle Home	12:57 PM	12:57 PM		
14	PTS : TSB : 21-2128 2021 F-150 - 3.5L PowerBoost - U0288 In The SOBDMC	12:57 PM	12:57 PM		
15	PTS : OTA Dashboard	12:57 PM	12:57 PM		
16	PTS : Connected Vehicle Home	12:57 PM	12:57 PM		
17	PTS : OTA Dashboard	12:57 PM	12:57 PM		
18	PTS : VIN 1FTFW1ED4MFA05912	2:01 PM	2:01 PM		
19	pts:connectedVehicle	2:01 PM	2:01 PM		
20	PTS : FSA : 21G01	2:01 PM	2:01 PM		
21	Network Test	2:08 PM	2:09 PM	JavaNTest	
22	Self Test	2:09 PM	5:39 PM		
23	Powertrain Control Module (PCM) Software Update	2:17 PM	2:33 PM	G2176846	
24	Anti-Lock Brake System (ABS) Module Software Update	2:22 PM	2:33 PM	G2199389	
25	Secondary On-Board Diagnostic Control Module C (SOBDMC) Software Update	2:27 PM	2:33 PM	G2174942	
26	Battery Energy Control Module (BECM) Software Update	2:30 PM	2:33 PM	G2232623	
27	PTS : Workshop Manual : 2021 F-150	3:10 PM	3:10 PM	SM2	
28	PTS : Workshop Manual : 418-01B Module Configuration - Vehicles With: Over-the-Air (OTA) Programming::Diagnosis and Testing::Module Configuration	3:10 PM	3:10 PM	G2179886	
29	PTS : Workshop Manual : 418-01B Module Configuration - Vehicles With: Over-the-Air (OTA) Programming::Diagnosis and Testing::Module Configuration	3:10 PM	3:10 PM	G2179886	
30	PTS : Diagnostic G2179886:PINPOINT TEST B: OTA UPDATES HAVE NOT INSTALLED OR ARE DELAYED BEYOND 8 CALENDAR DAYS WITHOUT A FAULT MESSAGE DISPLAYED ON THE TOUCH SCREEN OR IN THE FORDPASS OR LINCOLN WAY APPS	3:11 PM	3:11 PM		
31	PTS : Workshop Manual : Quick Links::Master DTC Chart (All-Inclusive)	3:17 PM	3:17 PM	SM2masterdctindex	
32	PTS : Workshop Manual : 206-09 Anti-Lock Brake System (ABS) and Stability Control::Diagnosis and Testing::Anti-Lock Brake System (ABS) and Stability Control	3:18 PM	3:18 PM	G2198684	
33	PTS : Diagnostic G2198684:Single Step View:PINPOINT TEST Y: ABS (ANTI-LOCK BRAKE SYSTEM) MODULE INTERNAL FAULT CONCERN	3:18 PM	3:18 PM		
34	PTS : Diagnostic G2198684:Y1 GUIDED DIAGNOSTIC QUESTION	3:18 PM	3:18 PM		
35	PTS : Diagnostic G2198684:Y2 RECHECK THE ABS (ANTI-LOCK BRAKE SYSTEM) MODULE FOR DTCS	3:18 PM	3:18 PM		
36	PTS : Diagnostic G2198684:Y6 CHECK FOR CORRECT ABS MODULE OPERATION	3:18 PM	3:18 PM		

37	PTS : Diagnostic DTCs and Symptoms	3:19 PM	3:19 PM		
38	PTS : VIN 1FTFW1ED4MFA05912	3:22 PM	3:22 PM		
39	pts:connectedVehicle	3:22 PM	3:22 PM		
40	PTS : Workshop Manual : 2021 F-150	3:22 PM	3:22 PM	SM2	
41	PTS : Diagnostic DTCs and Symptoms	3:23 PM	3:23 PM		
42	PTS : TSB : 22-2151 2021 F-150 - 3.5L PowerBoost - Illuminated MIL With DTCs P0300, P0301-P0306, P0316, P050E, P1674, P0454 And/Or P2451 In The PCM - Built On Or Before 23-Apr-2021	3:23 PM	3:23 PM		
43	PTS : Workshop Manual : 206-09 Anti-Lock Brake System (ABS) and Stability Control::Removal and Installation::Electric Brake Booster (EBB)	3:25 PM	3:25 PM	G2165510	
44	PTS : VIN 1FTFW1ED4MFA05912	6:19 PM	6:19 PM		
45	pts:connectedVehicle	6:19 PM	6:19 PM		
46	PTS : Connected Vehicle Home	6:19 PM	6:19 PM		
47	PTS : VIN 1FTFW1ED4MFA05912	7:05 PM	7:05 PM		
48	pts:connectedVehicle	7:05 PM	7:05 PM		