

Last Vehicle Status Update: June 17, 2024 05:15 PM

*Note: Do not use as a pressure gauge

Refresh

Odometer



5934 Miles

Fuel Level



Fuel Level: 74%

Fuel Range: 441 Miles to empty

Tire Pressure (PSI)*



Recommended Tire Pressure(cold)

Front : 36 | Rear : 36

Oil Life Remaining



96%

12V Battery



Battery State of Charge : 76%
 Battery Voltage : 13.1V

60-Day VHA/DTC History

Last Vehicle Health Update: June 17, 2024 12:19 PM

April 2024

Sun	Mon	Tue	Wed	Thu
	1	2	3	4
7	8	9	10	11
14	15	16	17	18
21	22	23	24	25
28	29	30		

May 2024

Sun	Mon	Tue	Wed	Thu
			1	2
5	6	7	8	9
12	13	14	15	16
19	20	21	22	23
26	27	28	29	30

June 2024

Sun	Mon	Tue	Wed	Thu
2	3	4	5	6
9	10	11	12	13
16	17	18	19	20
23	24	25	26	27
30				

Vehicle Health Alerts (VHA) and Diagnostic Trouble Codes (DTC)

Date Time Odometer	Event Description	Module	DTC	FT	SB	TSB/GSB/SSM	Send to Search	Description
------------------------	-------------------	--------	-----	----	----	-------------	----------------	-------------

June 17, 2024

Time : 12:19 PM
 Odometer :
 5915 mi

IPMA | B152E : 08 : 28
 TCU | U0146 : 09 : 08 TSB

Select All

- Rear Camera 2
- Lost Communication With Serial Data Gateway Module 'A'

June 10, 2024

Select All

Time : 10:13 AM

Odometer :
5734 mi

★	IPMA		B152E: 08 : 28	
	TCU		U0146: 09 : 08	TSB

- ⚠ Rear Camera 2
- ⚠ Lost Communication With Serial Data Gateway Module 'A'

May 30, 2024

Select All

Time : 08:42 AM

Odometer :
5169 mi

★	IPMA		B152E: 08 : 2F	
★	IPMA		B1578: 89 : 2C	
★	TCU		U0146: 09 : 08	TSB

- ⚠ Rear Camera 2
- ⚠ Digital Park Assist Camera Vision System
- ⚠ Lost Communication With Serial Data Gateway Module 'A'

May 28, 2024

Select All

Time : 04:33 PM

Odometer :
5137 mi

★	TCU		U0146: 09 : 0A	TSB
	IPMA		B1578: 89 : 28	

- ⚠ Lost Communication With Serial Data Gateway Module 'A'
- ⚠ Digital Park Assist Camera Vision System

Time : 04:11 PM

Odometer :
5128 mi

★	GWM		U2402: 00 : 49	TSB
	IPMA		B1578: 89 : 28	
	TCU		U0146: 09 : 0B	TSB

- ⚠ Ethernet Failure With Telematic Control Unit Module (TCU)
- ⚠ Digital Park Assist Camera Vision System
- ⚠ Lost Communication With Serial Data Gateway Module 'A'

May 27, 2024

Select All

Time : 09:30 AM

Odometer :
5124 mi

	IPMA		B1578: 89 : 28	
	TCU		U0146: 09 : 0B	TSB

- ⚠ Digital Park Assist Camera Vision System
- ⚠ Lost Communication With Serial Data Gateway Module 'A'

Time : 09:25 AM

Odometer :
5123 mi

★	IPMA		B1578: 89 : 28	
★	TCU		U0146: 09 : 0B	TSB

- ⚠ Digital Park Assist Camera Vision System
- ⚠ Lost Communication With Serial Data Gateway Module 'A'

May 26, 2024

Select All

Time : 08:03 PM

Odometer :

5097 mi

★ IPMA | B1578 : 89 : 2E

⚠ Digital Park Assist Camera Vision System

May 24, 2024

Select All

Time : 06:46 AM

Odometer :

5064 mi

★ PSCM | U3003 : 68 : 2E

⚠ Battery Voltage

May 23, 2024

Select All

Time : 08:21 AM

Odometer :

5053 mi

★ IPMA | B1578 : 89 : 2E

⚠ Digital Park Assist Camera Vision System

★ PSCM | U3003 : 68 : 28

⚠ Battery Voltage

May 22, 2024

Select All

Time : 08:41 AM

Odometer :

5034 mi

★ PSCM | U3003 : 68 : 2E

⚠ Battery Voltage

May 03, 2024

Select All

Time : 08:27 PM

Odometer :

4456 mi

★ IPMA | B152E : 08 : 28

⚠ Rear Camera 2

★ PSCM | U3003 : 68 : 2C

⚠ Battery Voltage

TCU | U0146 : 09 : 08 TSB

⚠ Lost Communication With Serial Data Gateway Module 'A'

Time : 09:17 AM

Odometer :

4454 mi

★ IPMA | B152E : 08 : 2C

⚠ Rear Camera 2

TCU | U0146 : 09 : 08 TSB

⚠ Lost Communication With Serial Data Gateway Module 'A'

April 28, 2024

Select All

Time : 09:03 AM

Odometer :
4346 mi

★ IPMA		B152E : 08 : 28	
TCU		U0146 : 09 : 08	TSB
TRM		U0140 : 87 : 08	TSB

- ⚠ Rear Camera 2
- ⚠ Lost Communication With Serial Data Gateway Module 'A'
- ⚠ Lost Communication With Body Control Module

April 26, 2024

Select All

Time : 12:16 PM

Odometer :
4176 mi

TRM		U0140 : 87 : 08	TSB
TCU		U0146 : 09 : 08	TSB

- ⚠ Lost Communication With Body Control Module
- ⚠ Lost Communication With Serial Data Gateway Module 'A'

April 24, 2024

Time : 08:48 PM

 OTA On-Vehicle
Activity-Update
Activation is
finished

Time : 08:45 PM

 OTA On-Vehicle
Activity-Vehicle
Activation Start

Time : 08:44 PM

 OTA On-Vehicle
Activity-Vehicle
Activation Start

April 23, 2024

Select All

Time : 06:05 PM

Odometer :
4055 mi

IPMA		B152E : 08 : 28	
TRM		U0140 : 87 : 08	TSB
TCU		U0146 : 09 : 08	TSB

- ⚠ Rear Camera 2
- ⚠ Lost Communication With Body Control Module
- ⚠ Lost Communication With Serial Data Gateway Module 'A'

April 22, 2024

Time : 11:54 AM



New Alert - Time to Plan

Odometer :

4022 mi

April 20, 2024

Select All

Time : 05:38 PM

Odometer :

3964 mi

★	TCU		U0146:09:08	TSB
	IPMA		B152E:08:28	
	TRM		U0140:87:08	TSB
	TRM		U0143:87:08	TSB

- ⚠ Lost Communication With Serial Data Gateway Module 'A'
- ⚠ Rear Camera 2
- ⚠ Lost Communication With Body Control Module
- ⚠ Lost Communication With Body Control Module 'C'

Time : 05:01 PM

Odometer :

3956 mi

★	GWM		U2402:0A:0B	
★	TCU		U0146:09:0B	TSB
	IPMA		B152E:08:28	
	TRM		U0140:87:08	TSB
	TRM		U0143:87:08	TSB

- ⚠ Ethernet Failure With Telematic Control Unit Module (TCU)
- ⚠ Lost Communication With Serial Data Gateway Module 'A'
- ⚠ Rear Camera 2
- ⚠ Lost Communication With Body Control Module
- ⚠ Lost Communication With Body Control Module 'C'

Time : 04:50 PM

Odometer :

3954 mi

★	IPMA		B152E:08:28	
★	TCU		U0146:09:08	TSB
★	TRM		U0143:87:08	TSB
★	TRM		U0140:87:08	TSB

- ⚠ Rear Camera 2
- ⚠ Lost Communication With Serial Data Gateway Module 'A'
- ⚠ Lost Communication With Body Control Module 'C'
- ⚠ Lost Communication With Body Control Module